

ASS. REC. BY: Taufikh

REF:

NS/ INC 22007794/Tvc

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: **SMS 5345T**  
 Policy No. \_\_\_\_\_  
 Claims No. **MT/1184383-002**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: S4D301OK Yr Regn: 2016 June  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Mynden 140 C.C. 1685  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 640763 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KMHLB414MG4091536  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 205/60R16  
 R: 1  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Wostahle  
 Front R/Bal. 6 mm Rear R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 10/8/2022 D.O.I. 10/8/22  
 Survey held at Comfort by jay  
 Des. of Damages: Frit / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS WP  
 Date: \_\_\_\_\_ Person Contacted: Lim TS Vehicle: IN / OUT

Date / Time	Action / Instruction
28/9/22	Taufikh informed LS \$1700 (Red 4972.78, 74%)

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) 28/9/22-typist

Report Format: TP  
 Lump Sum / L.B.H. (\$) \$1700

Days Of Repair: 3  
 Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invs (\$) \_\_\_\_\_  
 : Weekend (\$) \_\_\_\_\_

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS. \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 10.08.2022

INSURANCE: NTUC (US)

MODEL: Hyundai i40

MVA: LIM T S

VEHICLE NO.: SHD3010K

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Door LH	1		\$ 2,707.70
	Rear Door LH	1		\$ 2,201.10
	Rocker Panel Garnish LH	1		\$ 732.80
	<b>SUB TOTAL</b>			\$ 5,641.60
	<b>LESS 20%</b>			\$ 1,128.32
	<b>DISCOUNTED TOTAL</b>			\$ 4,513.28
	Front Door ComfortDelGro LH	1		\$ 75.00
	Rear Door APPS LH	1		\$ 80.00
	<b>S/NETT SUB</b>			\$ 155.00
	<b>LESS 10%</b>			\$ 15.50
	<b>S/NETT TOTAL</b>			\$ 139.50
	<b>SPARE PARTS TOTAL</b>			\$ 4,652.78
	<b>Labour Charge</b>			
	Panel Beating - Rear Fender Arch LH			\$ 800.00
	Spray Painting Charge			\$ 900.00
	Tuff Kote			\$ 80.00
	Transfer Of Doors	2	\$ 120.00	\$ 240.00
	<b>TOTAL LABOUR</b>			\$ 2,020.00
	<b>ESTIMATE TOTAL</b>			\$ 6,672.78

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taufik 97495749  
 WP 10/8/22 @ 4pm  
 US Resurvey after repair  
 3 days  
 tafik@lkkauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

m: ARC Repair TP(CLS0)1

**JOB CARD** Sales Order: 4523002

JC No: 805526047


OWNER  IS COMFORT TRANSPORTATION PTE LTD 7010045 OWNER NO. ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P)  IDENTIFICATION CARD NO.	REGN NO: <b>SHD3010K</b>	MILEAGE
	MAKE: <b>HYUNDAI</b>	FUEL E.....1/2.....F
	MODEL <b>I-40</b>	DATE/TIME IN <b>10.08.2022 12:20</b>
	YR OF MANU. <b>09.06.2016</b>	TARGET DATE
	CHASSIS CODE <b>KMHLB41UMGU091336</b>	COMPLETION DATE/TIME:

JOB DESCRIPTION

Ident Date: 10.08.2022  
 DURE: 3P 10.08.2022/C

NO LABOR CODE  
 0010 PB

DESCRIPTION  
 PANEL BEATING-SHD3010K-TP



RECEIVED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
 SERVICE ADVISOR

\_\_\_\_\_  
 CUSTOMER'S SIGNATURE

Identification Slip

Exit Pass

No.: SHD3010K

LIMITS

Vehicle No.:

SHD3010K

\_\_\_\_\_  
 Service Advisor

\_\_\_\_\_  
 Signature/Date

\_\_\_\_\_  
 Name of Service Advisor

\_\_\_\_\_  
 Date

Returned to Service Reception upon collection

To be kept by Security Guard