

SAS-KIV

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

DATE: 10.08.2022

INSURANCE: NTUC (US)

MODEL: Hyundai i40

MVA: LIM T S

VEHICLE NO.: SHD3010K

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Door LH	1		\$ 2,707.70
	Rear Door LH	1		\$ 2,201.10
	Rocker Panel Garnish LH	1		\$ 732.80
	SUB TOTAL		732.80	\$ 5,641.60
	LESS 20%		586.24	\$ 1,128.32
	DISCOUNTED TOTAL			\$ 4,513.28
	Front Door ComfortDelGro LH	1		\$ 75.00
	Rear Door APPS LH	1		\$ 80.00
	S/NETT SUB			\$ 155.00
	LESS 10%			\$ 15.50
	S/NETT TOTAL			\$ 139.50
	SPARE PARTS TOTAL			\$ 4,652.78
	Labour Charge			
	Panel Beating - Rear Fender Arch LH			\$ 800.00
	Spray Painting Charge			\$ 900.00
	Tuff Kote			\$ 80.00
	Transfer Of Doors	2	\$ 120.00	\$ 240.00
	TOTAL LABOUR			\$ 2,020.00
	ESTIMATE TOTAL			\$ 6,672.78

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfui 97495749
 WP 10/8/22 @ 4pm
 US Resurvey after repair
 03 days
 tanfui@lkkauto.com

RY
 RY
 732.80
 732.80
 cut -
 cut -
 525
 850
 200
 200
 1375
 2100.74
 US\$1700

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Thrd party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: