

ASS. REC. BY: Taufik

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. MT/1190712-001

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Chiaing Vehicle: IN / OUTVeh No: SH8097B Yr Regn: 2019 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai / Coniq C.C. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 255505 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KM HC851CVC4164964Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 RTR: 2 -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WestlakeFront R/Bal. 6 mmL/Bal. 6 mmD.O.A. _____ D.O.I. 10/8/22Survey held at Confort Cony

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh finalised LS \$900, 2 days. (Red \$1424.80, 61%)

Date/Time, File Pass to?

1) 29/09/22

Date/Time, File Return to?

2) _____

Rep. Format: TPLump Sum / L.B. / F. 900Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH8097B

10.08.22

MAKE REG 01.08.2019

CHIANG/ NUTC

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
2	REAR BUMPER SIDE BRACKET LH		\$55.80
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR BUMPER CENTRE MOULDING		\$451.25
2	REAR BUMPER REFLECTOR LH		\$41.50
10	REAR BUMPER CLIPS		\$22.00
	SUB TOTAL		\$1,424.75
	20.00%		\$284.95
	DISCOUNTED TOTAL		\$1,139.80
1	REAR FENDER ADVERTISEMENT		\$100.00
1	REAR BUMPER ADVERTISEMENT		\$55.00
			\$155.00
	Labour Charge		
	Panel Beating		\$550.00
	Spray Painting Charge		\$300.00
	Check Lighting and Wiring		\$60.00
	Tuff Kote		\$60.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$1,030.00
	ESTIMATE TOTAL		\$2,324.80
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tan Kah 92495749
 'UP' 10/8/22 @ 430pm
 2 delays
 45 mins after repair
 Tan Kah & Lim Han

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 10.08.2022 12:47

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4522947

JC NO: 805526040

CUSTOMER

R/MS COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717

TEL. (R) 65508755

(O)

(P)

DISCOUNT CARD NO.

REGN NO.:

SH 8097B

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 10.08.2022 12:00

YR OF MANU.

01.08.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164964


COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 03.08.2022

INCIDENT: 3P 03.08.2022

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

Re:

No.: SH 8097B CHIANG

Vehicle No.: SH 8097B

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard