

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No : 305526042
Date : 18.08.22

FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SH 9943C

Date of Accident : 10.08.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- XE5048U
2. The finalized amount shall be:
 - (a) Spare Parts after List discount _____
 - (b) Labour Charges (include advertisement stickers etc,if any) _____
 - Total for Part-By-Part Repair Cost** _____
 - (c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: <u>20%</u>	\$15,150.00
Final Lumpsum Repair cost	\$15,150.00
3. Estimated normal period for repairs: 6 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : TAUFIKH
Date : 29/9/22

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00	Y		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

LKK - Taufiq

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

PAGE 1 of 2

DATE: 10.08.2022

FRONT

MODEL: Hyundai Ioniq

INSURANCE: NTUC (L/S)

VEHICLE NO.: SH 9943C

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Radiator Grille	1		\$ 1,409.10
	Front Bumper Cover	1		\$ 481.10
	Front Bumper Moulding Centre Upper	1		\$ 368.50
	Front Bumper Grille LH / RH	2	\$ 93.45	\$ 186.90
	Front Bumper Towing Cover	1		\$ 29.00
	Front Bumper Lower Moulding	1		\$ 368.50
	Front Bumper Lower Stiffner	1		\$ 285.10
	Front Bumper Lip	1		\$ 35.10
	Front Bumper Bracket Top (LH/RH)	2	\$ 35.00	\$ 70.00
	Front Bumper Bracket (LH/RH)	2	\$ 28.00	\$ 56.00
	Front Bumper Clips 10 pcs	10	\$ 2.20	\$ 22.00
	Front Bumper Lower Grille	1		\$ 365.30
	Headlamp Support Panel Assy	1		\$ 949.30
	Headlamp LH / RH	2	\$ 2,110.30	\$ 4,220.60
	Day Light ,LH / RH	2	\$ 642.50	\$ 1,285.00
	Front Fender Shield LH	1		\$ 164.70
	Flap Assy Active Air Upper LH	1		\$ 824.60
	Actuator Active Air LH	1		\$ 257.10
	Front Fender LH	1		\$ 588.80
	Bonnet	1		\$ 2,253.80
	Radiator Inverter	1		\$ 884.80
	Radiator	1		\$ 710.50
	Radiator Fan Motor	1		\$ 576.00
	Radiator Fan	1		\$ 375.10
	Air Con Condenser	1		\$ 663.60
	SUB TOTAL			\$ 17,430.50
	LESS 20%			\$ 3,486.10
	DISCOUNTED TOTAL			\$ 13,944.40
	Front No. Plate With Trim Cover	1		\$ 55.00
	LESS 10%			\$ 5.50
	NETT TOTAL			\$ 49.50
	SPARE PARTS TOTAL			\$ 13,993.90
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 1,200.00
	Wiring Charge			\$ 40.00
	Tuff Kote			\$ 40.00
	R/I AIR CON CONDENSER ETC			\$ 150.00
	TOWING FEE -			NIL
	TOTAL LABOUR			\$ 2,630.00
	ESTIMATE TOTAL			\$ 16,623.90

13661.80
2732.36
\$10929.44

17

Taufiq 92495747
WP 10/8/22 @ 430pm
L/S Resing after repair
Taufiq e/Handson
3 days

700
750
30
30
100? plus

\$1610.00

\$12588.94A

REPAIR ESTIMATE

LKK - Taufikh

DATE: 10.08.2022

REAR

Page 2 of 2

MODEL: Hyundai Ioniq

INSURANCE: NTUC (L/S)

VEHICLE NO.: SH 9943C

MVA: LIMITS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Reinforcement	1		\$ 394.80
	Rear Bumper Reinforcement Bracket LH/RH	2	\$ 138.10	\$ 276.20
	Rear Bumper Side Brackets LH/RH	2	\$ 55.80	\$ 111.60
	Rear Bumper Centre Moulding Assy	1		\$ 451.25
	Rear Bumper Lower Centre Moulding Assy	1		\$ 155.00
	Rear Bumper Under Cover	1		\$ 225.00
	Rear Bumper Cover Clips	10	\$ 2.20	\$ 22.00
	Rear Bumper Reflector Lamp LH/RH	2	\$ 41.45	\$ 82.90
	Rear Bumper Tow Cover	1		\$ 98.80
	BootLid Emblem - Hybrid	1		\$ 24.30
	BootLid Emblem - Ioniq	1		\$ 31.30
	BootLid Assy	1		\$ 2,480.40
	BootLid Lamp LH/RH	2	\$ 794.40	\$ 1,588.80
	Taillamp LH/RH	2	\$ 870.40	\$ 1,740.80
	Rear End Panel	1		\$ 532.00
	Rear End Panel Garnish	1		\$ 346.80
	Rear Smart Key Antenna	1		\$ 40.50
	Rear Foglamp	1		\$ 201.50
	SUB TOTAL			\$ 9,263.35
	LESS 20%			\$ 1,852.67
	DISCOUNTED TOTAL			\$ 7,410.68
	BootLid ComfortDelGro	1		\$ 35.00
	BootLid 65521111	1		\$ 35.00
	BootLid APPS	1		\$ 40.00
	Reverse Sensors	1		\$ 180.00
	Rear No. Plate With Trim Cover	1		\$ 55.00
	Rear Windscreen Sealant	2	\$ 46.00	\$ 92.00
	S/NETT SUB			\$ 437.00
	LESS 10%			\$ 43.70
	S/NETT TOTAL			\$ 393.30
	Rear Bumper Mat	1		\$ 50.00
	SPARE PARTS TOTAL			\$ 7,853.98
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 1,200.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Remove/Refix Rear Windscreen Glasses			\$ 250.00
	TOTAL LABOUR			\$ 2,770.00
	ESTIMATE TOTAL			\$ 10,623.98

3670.15
734.03
\$ 2936.12

382.00
38.20
\$ 343.80

S/NETT

525
750
30
180

\$ 1485.00
\$ 4764.92 B

Taufikh 97495747
w/ 10/8/22 @ 430pm
L/S rising after report
sample & look out
3 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORT DELGRO ENGINEERING

VEHICLE : SH 9943C TYPE OF CLAIM : TP
 MODEL : HYUNDAI IONIQ SURVEYED BY : LKK-TAUFIKH
 JOB NO : 305526042 DATE : 10.08.22

SUPPLEMENTARY OF PARTS AND LABOUR COSTS

S/No	DESCRIPTION	QTY	ESTIMATE \$	REMARKS
1	BONNET HINGE RH/LH	2	118.70	Each
2	BONNET LOCK	1	127.30	
3	FRONT BUMPER REINFORCEMENT	1	1136.70	
4	HORN WIRE	1	386.70	
	* Last Entry *			
			\$ 1888.10	
			Less 20%	

\$ 1510.48 C

$A+B+C = \$ 18914.34$
Less 20%

4S \$ 15150.00