

ASS. REC. BY: Taufikh

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: MS Luke Vehicle: IN / OUT

Veh No: SHD8576L Yr Regn: 20/6/1 Sep.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 c.c. 1685

Colour: Yellow A/C: Insured / Std / NI / NA

Sp. Reading: 859937 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 104 HLB4/1049 4093752

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Workshop

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 10/8/22

Survey held at Comfort Logon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh finalised LS \$1200, 2 days (Red \$880.82, 42%)

Date/Time, File Pass to? : Preli. Report
 : Final Report

1) Date/Time, File Return to?

2) _____

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
_____ S + RS. _____ SI	
Photos	
Others	
TOTAL	

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Report Format: TP

Lump Sum / B.B. \$ 1200

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4522864


JC No: 305525881

CUSTOMER NAME: CITYCAB PTE LTD VMS NO: 7010070 CUSTOMER NO: 383 SIN MING DRIVE ADDRESS: Singapore SINGAPORE 575717 TEL: (R) 65551188 (O) (P)	REGN NO: SHD8576L	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: I-40	DATE/TIME IN 08.08.2022 15:50
	YR OF MANU: 15.09.2016	TARGET DATE
	CHASSIS CODE: KMHLB41UMGU093752	COMPLETION DATE/TIME:

Accident Date: 08.08.2022
 Accurrence: 3P 08.08.2022

JOB DESCRIPTION

/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHD8576L** **YY**

Vehicle No.: **SHD8576L**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD8576L

Date: 10/08/2022

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. LOKE Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 553.00
1	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER LOWER COVER			\$ 228.00
1	REAR BUMPER REINFORCEMENT			\$ 428.40
	SUB TOTAL			\$ 1,231.40
	LESS 20%			\$ 246.28
	DISCOUNTED TOTAL			\$ 985.12
	REAR BUMPER RUBBER MAT			\$ 50.00
	REAR BUMPER REVERSE SENSOR			\$ 135.70
	REAR FENDER ADVERTISEMENT LOGO LH			\$ 100.00
	REAR FENDER ADVERTISEMENT LOGO RH			\$ 100.00
	REAR BUMPER ADVERTISEMENT LOGO			\$ 50.00
				\$ 435.70
	Labour Charge			
	PANEL BEATING			\$ 300.00
	SPRAY PAINTING CHARGE			\$ 300.00
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00
	TOTAL LABOUR			\$ 660.00
	ESTIMATE TOTAL			\$ 2,080.82

Handwritten notes:
 ke
 net
 dl
 ?

Handwritten notes:
 Net
 Net
 Net
 Net
 Net

Handwritten notes:
 280
 250
 30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Handwritten notes:
 Tanjini 17495717
 up 10/8/22 @ 430 pm
 2 days
 to busy after repair
 sent for client

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
