





**COMFORT TRANSPORTATION PTE LTD**

**REPAIR ESTIMATE**

Vehicle No. : SHD8576L

Date: 10/08/2022

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. LOKE Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 553.00
1	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER LOWER COVER			\$ 228.00
1	REAR BUMPER REINFORCEMENT			\$ 428.40
	<b>SUB TOTAL</b>			\$ 1,231.40
	<b>LESS 20%</b>			\$ 246.28
	<b>DISCOUNTED TOTAL</b>			<b>\$ 985.12</b>
	REAR BUMPER RUBBER MAT			\$ 50.00
	REAR BUMPER REVERSE SENSOR			\$ 135.70
	REAR FENDER ADVERTISEMENT LOGO LH			\$ 100.00
	REAR FENDER ADVERTISEMENT LOGO RH			\$ 100.00
	REAR BUMPER ADVERTISEMENT LOGO			\$ 50.00
				<b>\$ 435.70</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$ 300.00
	SPRAY PAINTING CHARGE			\$ 300.00
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00
	<b>TOTAL LABOUR</b>			<b>\$ 660.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,080.82</b>

*Handwritten notes:*  
 ke-  
 net-  
 dl-  
 P-  
 1

*Handwritten notes:*  
 Netty-  
 Nett-  
 Nett na-  
 Nett-  
 Nett-  
 Nett

*Handwritten notes:*  
 280  
 250  
 30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Handwritten notes:*  
 Tanjini 17495717  
 up/ 10/8/22 @ 430 pm  
 2 days  
 to busy after repair  
 sent for client

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 \_\_\_\_\_