

ASS. REC:BY: Taufik

REF:

NS/ INC 22007799/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **SJR 6140B**

Policy No: _____

Claims No: **MT/1184114-002**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: clung

Vehicle: IN / OUT

Veh No: **SH4 7950L** Yr Regn: **20.9.0ct**

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Hyundai** C.C. **1580**

Colour: **Blue** A/C: Insured / Std / NI / NA

Sp. Reading: **258645** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **KMHC 85102418700**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **145/65R15**

R: **u n**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **Wesfike**

Front: _____ Rear: _____

R/Bal. **6** mm R/Bal. **6** mm

L/Bal. **6** mm L/Bal. **6** mm

D.O.A. **11/8/2022** D.O.I. **11/8/22**

Survey held at **Comfort 6 gang**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/9/22 Taufik informed LS \$950 (red 1869.42, 66%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 29/9/22-typist

Rep. Format: **TP**

Lump Sum / L.B. / : **\$950**

Days Of Repair: **2**

Resurvey No. of Trip: **1**

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS. ____ SI

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA7950L

11.08.2022

MAKE REG. 25.10.2019

CHIANG/NTUC

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		RV \$459.40
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80 X \$111.60
10	REAR BUMPER CLIPS		\$2.20 new \$22.00
1	REAR BUMPER CENTRE MOULDING		del \$451.25
1	REAR BUMPER REINFORCEMENT		? \$394.80
1	REAR REINFORCEMENT STAY /RH		\$138.10 ? \$138.10
1	REAR BUMPER LOWER MOULDING		X \$155.00
2	REAR BUMPER REFLECTOR /RH		\$41.45 X \$41.45
1	REAR BUMPER TOW COVER		X \$98.80
	SUB TOTAL		\$1,872.40
	20.00%		\$374.48
	DISCOUNTED TOTAL		\$1,497.92
1	REAR NUMBER PLATE W/HOLDER		cur \$55.00
1	REAR REVERSE SENSOR		new \$180.00
			\$211.50
	Labour Charge		
	Panel Beating		350 \$600.00
	Spray Painting Charge		250 \$300.00
	Tuff Coating		X \$90.00
	Check Wiring and Lighting		X \$60.00
	Remove/refix Reverse sensor		30 \$60.00
	TOTAL LABOUR		\$1,110.00
	ESTIMATE TOTAL		\$2,819.42
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanjiu 92 495749
 WP' 11/8/22 E 4pm
 62 days
 L3 Repair after repair
 Tanjiu Chhannam

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Date/Time: 11.08.2022 15:38

Page : 1

eam: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4525012

JC NO: 805526208


CUSTOMER		REGN NO: SHA7950L	MILEAGE
3/MS COMFORT TRANSPORTATION PTE LTD		MAKE: HYUNDAI	FUEL
CUSTOMER NO. 7010045		MODEL IONIQ(G3)	DATE/TIME IN 11.08.2022 12:45
ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717			TARGET DATE
L. (R) 65508755 (O)		YR OF MANU. 25.10.2019	COMPLETION DATE/TIME:
(P)		CHASSIS CODE KMHC851CVLUJ187210	
SCOUNT CARD NO.			

JOB DESCRIPTION

ccident Date: 11.08.2022

ATURE: 3P 11.08.2022

/NO LABOR CODE DESCRIPTION



IECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

3:
O.:
le No.: SHA7950L CHIANG

Vehicle No.: SHA7950L

3 of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard