

ASS. REC:BY: Taujau

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Chung

Vehicle: IN / OUT

Veh No: SHA 7950L Yr Regn: 24.9.0ct

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Hyundai Long C.C. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 258645 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KUHC 85102418700

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 145/65R15

R: u

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wesfike

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 11/8/22

Survey held at Comfort 6 gang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / I.B.R. (%) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

____ S + RS. ____ SI

Photos

Others

TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA7950L

11.08.2022

MAKE REG. 25.10.2019

CHIANG/NTUC

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		RV \$459.40
1	REAR BUMPER SIDE BRACKET LH/RH		\$55.80 X \$111.60
10	REAR BUMPER CLIPS		\$2.20 net \$22.00
1	REAR BUMPER CENTRE MOULDING		del \$451.25
1	REAR BUMPER REINFORCEMENT		? \$394.80
1	REAR REINFORCEMENT STAY /RH		\$138.10 ? \$138.10
1	REAR BUMPER LOWER MOULDING		X \$155.00
2	REAR BUMPER REFLECTOR /RH		\$41.45 X \$41.45
1	REAR BUMPER TOW COVER		X \$98.80
	SUB TOTAL		\$1,872.40
	20.00%		\$374.48
	DISCOUNTED TOTAL		\$1,497.92
1	REAR NUMBER PLATE W/HOLDER		am \$55.00
1	REAR REVERSE SENSOR		am \$180.00
			\$211.50
	Labour Charge		
	Panel Beating		350 \$600.00
	Spray Painting Charge		250 \$300.00
	Tuff Coating		X \$90.00
	Check Wiring and Lighting		X \$60.00
	Remove/refix Reverse sensor		30 \$60.00
	TOTAL LABOUR		\$1,110.00
	ESTIMATE TOTAL		\$2,819.42
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanjiu 92 495749
 WP' 11/8/22 4pm
 62 days
 L3 Repair after repair
 Tanjiu Chhannam

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Date/Time: 11.08.2022 15:38

Page : 1

eam: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4525012

JC No: 805526208


CUSTOMER		REGN NO. SHA7950L	MILEAGE
3/MS COMFORT TRANSPORTATION PTE LTD		MAKE HYUNDAI	FUEL
CUSTOMER NO. 7010045		MODEL IONIQ(G3)	DATE/TIME IN 11.08.2022 12:45
ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717			TARGET DATE
L. (R) 65508755 (O)		YR OF MANU. 25.10.2019	COMPLETION DATE/TIME:
(P)		CHASSIS CODE KMHC851CVLUJ187210	
SCOUNT CARD NO.			

JOB DESCRIPTION

Accident Date: 11.08.2022

ATURE: 3P 11.08.2022

/NO LABOR CODE DESCRIPTION



HECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

3:
O.:
le No.: SHA7950L CHIANG

Vehicle No.: SHA7950L

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard