

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 25 Aug 2022

Preliminary Advice

Insured : SLN8014S
Vehicle No
TP Vehicle : SMM5556H
No
Make : HONDA FREED HYBRID SENSING
Date of : 16/08/2022
Inspection
Accident Date : 12/08/2022
Assignment Date : 17/08/2022
Est. Duration of Repair : 5
Inspection At : 2ND AUTO PTE LTD (HQ)
15 KAKI BUKIT ROAD 4, #01-05/53 BARTLEY BIZ CENTRE
SINGAPORE 417808

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,604.80
Revised Amount	:S\$	5,065.92
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,065.92

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 - () The vehicle is not economical for repair
 - () Part-by-Part repair
 - (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.