



SMM5556H Honda Freed

No	Qty	Parts Description		Estimated Parts Price	
1	1	Rear bumper assy	841.10	\$ 1,207.90	✓
2	2	Rear bumper bracket	NS	\$ 125.60	X
3	2	Rear bumper retainer	45.50	\$ 126.80	IPC
4	1	Rear bumper tow cover	11	\$ 66.30	X
5	2	Rear bumper reflector	11	\$ 303.60	X
6	1	Rear tailgate assy	1245.30	\$ 1,857.20	✓
7	1	Rear tailgate inner trim board	11	\$ 232.80	X
8	1	Rear tailgate inner trim board inner handle	11	\$ 86.20	X
9	1	Rear tailgate weatherstrip	245.10	\$ 288.60	✓
10	1	Rear tailgate lock mechanism	301	\$ 188.20	✓
11	1	Rear tailgate lock catch	11	\$ 86.70	X
12	1	Rear tailgate lock switch	11	\$ 215.30	X
13	1	Rear tailgate inner handle	11	\$ 88.60	X
14	1	Rear tailgate outer chrome garnish	11	\$ 240.20	X
15	1	Rear tailgate center logo	38.00	\$ 68.80	✓
16	1	Rear tailgate 'freed' emblem	111	\$ 66.50	✓
17	1	Rear tailgate 'hybrid' emblem	111	\$ 66.50	✓
18	2	Rear tailgate hinges	11	\$ 161.10	X
19	2	Rear tailgate damper	11	\$ 271.60	X
20	1	Rear tailgate wiper motor	11	\$ 579.40	X
21	1	Rear tailgate wiper blade assy	11	\$ 163.30	X
22	2	Rear tailgate no plate lamp	11	\$ 123.50	X
23	1	Rear end <del>lower</del> panel	541.00	\$ 841.70	✓
24	1	Rear end <del>lower</del> panel top garnish	111	\$ 129.90	✓
25	1	Rear windscreen glass moulding	112.80	\$ 188.90	✓
26	1	Rear tailgate left taillamp	11	\$ 440.20	X
27	1	Rear tailgate right taillamp	11	\$ 440.20	X
28	1	Rear left taillamp	11	\$ 605.10	X
29	1	Rear right taillamp	11	\$ 605.10	X
30	1	Rear left fender	11	\$ 1,272.50	X
31	1	Rear left fender inner garnish	11	\$ 435.20	X
32	1	Rear left fender inner cowl	11	\$ 218.90	X
33	1	Rear left air duct ventilator	11	\$ 88.60	X
				\$ 11,881.00	
Less 20%				\$ 2,376.20	
				\$ 9,504.80	

not Authorized  
 16/08/22  
 2/5 \$4000/  
 5 days.  
 Take parts after  
 repair



SMM5556H Honda Freed

No	Qty	Parts Description		Estimated Parts Price
		<u>Special Nett Items</u>		
1	<del>10</del> 1set	Rear bumper clips	111	\$ 50.00 40
2	4	Rear tailgate outer chrome garnish clips	11	\$ 30.00 X
3	8	Rear tailgate inner trim board clips	11	\$ 40.00 X
4	1	Rear end <del>lower</del> panel sealant	111	\$ 140.00 50
5	4	Rear end <del>lower</del> panel top garnish clips	11	\$ 30.00 X
6	1	Rear windscreen glass sealant	111	\$ 100.00 40
7	1	Rear windscreen glass rubber seal	111	\$ 100.00 30
8	1set 2	Rear bumper reverse sensor	shorted	\$ 300.00 200
9	1	Rear no plate	11	\$ 100.00 X
10	10	Rear left fender inner garnish clips	11	\$ 40.00 X
11	6	Rear left fender inner cowling clips	11	\$ 30.00 X
12	1	Rear left quarter glass sealant	11	\$ 80.00 X
13	1	Rear left fender sealant	11	\$ 100.00 X
14	1	Rear view camera	11	\$ 450.00 X
				\$ 1,590.00
Total parts				\$ 11,094.80

**SMM5556H Honda Freed**

No	Description	Labour Charges	
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,200.00	600
2	To putty and spray painting rear portion.	\$ 1,200.00	900
3	To check rear lighting and wiring.	\$ 50.00	20
4	To remove and install rear tailgate lock mechanism.	\$ 80.00	60
5	To remove and install rear fuel tank to facilitate the repair.	\$ 180.00	X
6	To remove and install rear seat, inner garnish and trim to facilitate the repair.	\$ 180.00	80
7	To apply anti rust proofing to rear affected area.	\$ 140.00	60
8	To remove and install rear bumper reverse sensor.	\$ 80.00	50
9	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00	120
10	To remove and install rear view camera.	\$ 80.00	X
11	To remove and install rear left quarter glass.	\$ 80.00	X
12	Towing service.	\$ 100.00	X
<b>Total labour :</b>		<b>\$ 3,510.00</b>	

**Total parts : \$ 11,094.80**

**Total labour : \$ 3,510.00**

**Total repair cost : \$ 14,604.80**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3519.90

202

2815.92

360

1890

5065.92

202

4052.92