

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC1387S

Make : HYUNDAI

Model : IONIQ(G3)

Date: 12.08.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 481.10
10	FRT BUMPER CLIPS			\$ 22.00
1	FRT BUMPER SIDE BRACKET LH			\$ 28.00
1	FRT BUMPER CENTRE MOULDING UPPER			\$ 368.50
1	HEADLAMP LH			\$ 2,110.30
1	FRT BUMPER SIDE MOULDING LH			\$ 93.45
1	DAY LIGHT LH			\$ 642.50
1	FRT FENDER LH			\$ 588.80
1	EMBLEM - BLUE DRIVE LH			\$ 26.60
1	FRT WHEEL HUB CAP LH			\$ 346.40
	SUB TOTAL		4065.15	\$ 4,707.65
	LESS 20%			\$ 948.13
	DISCOUNTED TOTAL		3252.12	\$ 3,759.52
	FRT FENDER ADVERTISEMENT LH		100	\$ 100.00
				\$ 100.00
	Labour Charge			
	PANEL BEATING			\$ 750.00
	SPRAY PAINTING CHARGE			\$ 600.00
	TUFF KOTE			\$ 60.00
	CHECK LIGHTING / WIRING			\$ 60.00
	TOTAL LABOUR		1085	\$ 1,470.00
	ESTIMATE TOTAL		4337.12	\$ 5,329.52
			4543.50	
			2 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Damage 92495349
 Reps 02/02/22 04pm
 1/8 hrs my after repair
 further @ 11hants. on
 (2) 3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: