

ASS. REC'DY: Tough

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated lost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

MS Loke

Veh No: 3HC8997K Yr Regn: 2022, July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1298

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 7833 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDKBSF4903096782

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 12/8/22

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Rep. Formet: _____

Lump Sum / I.B.R. (P

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC8997K

Date: 12/08/2022

Make : Toyota

Insurance: NTUC

Model : Prius

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT LEFT FENDER SUB ASSY			\$ 1,111.93
1	FRONT FENDER HYBRID EMBLEM LH			\$ 86.50
1	FRONT FENDER SHIELD LH			\$ 198.50
1	FRONT BUMPER COVER			\$ 586.18
1	FRONT BUMPER SIDE BRACKET LH			\$ 82.30
10	FRONT BUMPER CLIPS			\$ 22.00
1	HEADLAMP LH			\$ 2,735.28
1	FRONT BUMPER SIDE RETAINER LH			\$ 77.00
1	FRT BUMPER SIDE GRILLE			\$ 85.10
1	FRT BUMPER SPONGE			\$ 78.80
1	FRT BUMPER TOW COVER LH			\$ 28.38
1	FRT WHEEL RIM LH			\$ 1,570.55
	SUB TOTAL			\$ 6,662.52
	LESS 25%			\$ 1,665.63
	DISCOUNTED TOTAL			\$ 4,996.89
	FRT TYRE LH			\$ 216.00
				\$ 216.00
	Labour Charge			
	PANEL BEATING			\$ 1,100.00
	SPRAY PAINTING CHARGE			\$ 600.00
	TUFF KOTE			\$ 60.00
	CHECK ALL LIGHTING			\$ 60.00
	TOTAL LABOUR			\$ 1,820.00
	ESTIMATE TOTAL			\$ 7,032.89

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tafun 92445749
 'wr' 12/8/22 439m
 P/P Body before paint
 tafun dismantling
 2-3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4525130

JC NO: 305526303

STOMER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(R) (O)
(P)

COUNT CARD NO.

REGN NO:

SHC8997K

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4A11.08.2022 17:55

DATE/TIME IN

YR OF MANU.

21.07.2022

TARGET DATE

CHASSIS CODE


JTDKB3FU903096787

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 11.08.2022
ATURE: 3P 11.08.2022

NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

e No.: SHC8997K YY

Vehicle No.: SHC8997K

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard