

ASS. REC'D BY: Taujun

REF: CS/FCI 22007810/TCY3

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$42K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Ms Mary

Vehicle: IN / OUT

Veh No: 96912926 Yr Regn: 2017, June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350 C.C. 2488

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 159098 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNIMC2E26Z 0007976

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/15

R: 2 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 17/8/22

Survey held at Woon Meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.R. (\$) _____

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Adress : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate

To : MS First Capital Insurance Ltd
Motor Claims Dept

TP CLAIM

Date 16 Aug 2022

Dear Sirs :

Fax : 6507 3849

RE : ESTIMATE COST FOR NISSAN NV350 - GBG1292G

ACCIDENT INVOLVING GBG1292G & YM9786S ON 12/08/2022

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear mudguard o/s	1pc	Repair & spray R4
2	Rear bumper -nett	1pc	\$ 722.90 de ✓
3	Rear taillamp o/s -nett	1pc	\$ 289.80 org ✓
			\$ 1,012.70
<u>Labour Charge & Misc</u>			
	To remove, repair, replace & install rear damaged parts.	}	\$ 800.00 500
	To R & R wiring		\$ 60.00 30
	To putty & spray painting.		\$ 600.00 450
Total			<u>\$ 2,472.70</u>

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

Tanfer 97495749
wp' 17/8/22 @ 1030
1/3 Remy after repair
tanfer @ 11h15 on
3-4 days