

Date: 16/08/2022

Vehicle No: SMQ7753X

Model: TOYOTA VIOS 1.5E

Chassis: MR2B23F3701194292-2019

Reg.Year: 2019

*Not withered*  
*U/Ry & Repair After Pain*  
*8 days*

Third Party Insurer: AIG

Third Party Veh No: SFZ5246S

Date of Accident: 07/08/2022

Estimator: TING AN

Surveyor:

### ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAIL LAMP LH	1		<i>Per</i> \$390.00
2	REAR WINDSCREEN MOULDING	1		<i>Per</i> \$95.00
3	REAR BUMPER	1		<i>Ang com</i> \$545.00
4	REAR BUMPER SIDE BRACKET LH	1		<i>D-1</i> \$155.00
5	REAR BUMPER SEAL LH	1		\$75.00
6	REAR TAIL LAMP BRACKET LH	1		<i>Per</i> \$60.00
7	REAR BUMPER REFLECTOR LH	1		<i>Per</i> \$98.00
8	REAR FENDER LH	1		<i>Ry</i> \$907.00
9	REAR RIM LH <i>Pr?</i>	1		<i>Net</i> \$1,891.00
10	REAR ABSORBER LH	1		\$150.00
11	REAR WHEEL BEARING HUB LH	1		\$849.00
SUB TOTAL				\$5,215.00
LESS 25%				-\$1,303.75
PARTS TOTAL				\$3,911.25

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>Per</i> \$50.00
2	REAR WINDSCREEN SEALANT	1		<i>Per</i> \$80.00
3	REAR FENDER SHEILD CLIPS LH	1		<i>Per</i> \$30.00
S/N TOTAL				\$160.00

#### LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST REAR ACCIDENT AREAS & ETC. \$600.00 ✓

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR FENDER LH & ETC. \$600.00 *400*

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM LH & CUSHION UPHOLDSTERY SET & ETC. TO EFFECT REPLACE OF REAR FENDER LH. \$300.00 *100*

#### Head office

6 Kung Chong Road Singapore 159143  
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

#### Branch

9A Serangoon North Ave 5 Singapore 554500  
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

#### Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047  
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date:	16/08/2022	Third Party Insurer:	AIG
Vehicle No:	SMQ7753X	Third Party Veh No:	SFZ5246S
Model:	TOYOTA VIOS 1.5E	Date of Accident:	07/08/2022
Chassis:	MR2B23F3701194292-2019	Estimator:	TING AN
Reg.Year:	2019	Surveyor:	

LABOUR CHARGES TO REMOVE & REFIX REAR WINDSCREEN GLASS, REAR WINDSCREEN MOUDLING, REAR WINDSCREEN SEALANT & ETC.	\$150.00	<i>1201</i>
LABOUR CHARGES TO REMOVE & REPLACE REAR RIM LH, REAR ABSORBER LH, REAR WHEEL BEARING HUB LH & ETC.	\$250.00	<i>?</i>
TO WHEEL ALIGNMENT & BALANCING.	\$80.00	<i>201</i>
TO TUFF KOTE & UNDERSEAL MATERIALS.	\$120.00	<i>301</i>
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$80.00	<i>201</i>
	<b>LABOUR TOTAL</b>	<b>\$2,180.00</b>

TING AN	<b>TOTAL</b>	<b>\$6,251.25</b>
---------	--------------	-------------------