



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22007814/Eqy3m4 Date: 09/12/2022 Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	GBL 8926P
	Policy No.	20159249	Coverage (\$)	0.00
	Claim No.	M12D19202208	Excess (\$)	750.00
	Assign From	JOSEPHINE WONG	Assign Date	16/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	DFSK EC35	c.c	0
	Engine No.	HIDDEN	Year of Reg.	2022
	Chassis No.	LVPRPB4B1NC892594	Colour	SILVER
	Odometer	3246 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185 R14	MAXTREK	4 mm
	L/H Front Tyre	185 R14	MAXTREK	4 mm
	R/H Rear Tyre	185 R14	MAXTREK	4 mm
	L/H Rear Tyre	185 R14	MAXTREK	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	07/08/2022	Inspection Date	16/08/2022
	Survey held at	HONG SEH MOTORS PTE LTD 10 FOURTH LOK YANG ROAD JURONG TOWN SINGAPORE 628631		
5a. Remarks				
	A)THE MARKET VALUE IS S\$99,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days	