

Motor Claim Department United Overseas Insurance Limited 146 Robinson Road #0-01 UOI Building Singapore 068909

49.76

32.40

32.40

Josephinewong@UOI.com.sg

16 August 2022

1

1

1

\$

\$

\$

Dear Sir / Madam

12

13

14

RE: DFSK, Vehicle Reg.No: GBL8926P

We are pleased to submit Finalization for the repair of the above-mentioned vehicle:

Front Lh door window run channel

Front Lh door upper hinge

Front Lh door lower Hinge

| We are pleased to submit Finalization for the repair of the above-mentioned vehicle: | | | | | | |
|---|---|---|----|--------------------------------|--|--|
| 1 | Labour Description Remove, install & renew :- Front Lh fender, Lh headlamp , fender liner, Front Lh door ,Lh rocker panel , Fender Grills , wind mirror , door window Piller B, Lh sliding door . | | \$ | <u>Labour Cost</u> 3,600.00 | | |
| 2 Panel beating for Rocker panel inner , Piller B , Lh Siliding door , and Lh quoater panel | | | \$ | 3,200.00 | | |
| 3 | Computer Wheel Alignment - All 4 Wheels | | \$ | 200.00 | | |
| 4 | Transfer door fitting and window mechanism to new door | | \$ | 800.00 | | |
| 6 Respray premier & paint: Front Lh fender, Lh front door, Lh Siliding Door, Rocker panel, B piller, Center piller, Lh quarter panel and surface rear bumper B) Parts Qty | | | | | | |
| 1 | Front Lhs door | 1 | \$ | 678.42 | | |
| 2 | Front Lhs door inner trim | 1 | \$ | 265.85 | | |
| 3 | Front Lh door window | 1 | \$ | 99.35 | | |
| 4 | Front Lh door window outer grille | 1 | \$ | 41.17 | | |
| 5 | Front Lh door outer handle | 1 | \$ | 36.52 | | |
| 6 | Front Lh door window regulator | 1 | \$ | 124.73 | | |
| 7 | Front Lh door window motor | 1 | \$ | 220.56 | | |
| 8 | Side mirror LH assy | 1 | \$ | 148.10 | | |
| 9 | Side mirror Lh inner cover | 1 | \$ | 22.00 | | |
| 10 | Front Lh wheel mudguard | 1 | \$ | 42.31 | | |
| 11 | Front Lh Door inner window run moulding | 1 | \$ | 89.90 | | |

| 15 | Lh rocker panel | 1 | \$ 2,373.70 |
|----|---|----|-------------|
| - | | | |
| 16 | Lh piller B (between frt door and sliding dr) | 1 | \$ 1,987.90 |
| 17 | Front Lh door lock | 1 | \$ 48.99 |
| 18 | Front Lh door speaker JBL | 1 | \$ 230.00 |
| 19 | Front Lh door visor | 1 | \$ 35.00 |
| 20 | Front Door Step | 1 | \$ 30.15 |
| 21 | Front Rest Panel | 1 | \$ 40.24 |
| 22 | Front door clips | 12 | \$ 60.00 |
| 23 | | | |
| 24 | | | |
| 25 | | | |
| 26 | | | |
| 27 | | | |
| 28 | | | |
| 29 | | | |
| 30 | | | |
| 31 | | | |

TOTAL:

| Total Labour | \$ 12,000.00 |
|--------------------|-----------------|
| Total Parts | \$ 6,689.45 |
| 3 | \$ 18,689.45 |
| Plus 7% GST | \$ 1,308.26 |
| Grand Total | \$ 19,997.71 |

Should this repair job require any additional parts, we will inform you and bill you accordingly. Please confirm your acceptance of this quotation by sending us a return fax with your signature and company stamp on it.

| Yours sincerely, | | |
|------------------|---|--|
| - | / | |

I agree and accept the above quotation.

Hong Self Motors Pte Ltd

Workshop Department

Signature & Company stamp