



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/SMO22005735/Kcy3-1

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE #03-03
SINGAPORE LAND TOWERSINGAPORE 048623

Ref: ~~CS3/SMO22005735/Kcy3~~
Date: ~~10/06/2022~~ 12/0/2022
Code: SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBE 5390R	Veh. Inspected	GX 4054J
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2202073/AGC	Excess (\$)	0.00
Assign From	GRACE TEO AGNES CHAN	Assign Date	10/06/2022 12/08/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	13/06/2022	Inspection Date	17/06/2022
Survey held at	KWEE SENG MOTOR LTD BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-353 SINGAPORE 689538		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--