

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

437E

			Estimated
			Parts Price
		\$	2,550.00 <i>de - 991</i>
1	1	\$	128.00 <i>X nn</i>
2	2	\$	✓138.00 <i>KH de X</i>
3	2	\$	395.00 <i>X nn</i>
4	1	\$	893.00 <i>cut - 381.75</i>
5	1 set	\$	226.00 <i>X nn</i>
6	1	\$	226.00 <i>X nn</i>
7	1	\$	350.00 <i>cut - 122</i>
8	1	\$	129.00 <i>X nn</i>
9	1	\$	✓129.00 <i>cut -</i>
10	1	\$	589.00 <i>cut - 227</i>
11	1	\$	366.00 <i>X nn</i>
12	1	\$	678.00 <i>bt - 482.80</i>
13	1	\$	196.00 <i>X nn</i>
14	1	\$	196.00 <i>X nn</i>
15	1	\$	229.00 <i>cut -</i>
16	1	\$	88.00 <i>cut - 44</i>
17	1	\$	2,865.00
18	1	\$	488.00
19	1 set	\$	323.00
20	1 set	\$	160.00
21	2	\$	180.00 <i>cut -</i>
22	1 set	\$	65.00
23	1 set	\$	108.00 <i>cut -</i>
24	1	\$	1,465.00 <i>X nn</i>
25	1	\$	156.00 <i>X nn</i>
26	1	\$	156.00 <i>X nn</i>
27	1	\$	275.00 <i>X nn</i>
28	1	\$	4,886.00 <i>cut - 2486.10</i>
29	1	\$	2,210.00 <i>X nn</i>
30	1	\$	696.00 <i>bt -</i>
31	1	\$	148.00 <i>X nn</i>
32	1	\$	655.00 <i>cut - 606.80</i>
33	1	\$	1,481.00 <i>X R</i>
34	1	\$	120.00 <i>X nn</i>
35	1 set	\$	23,943.00
Less 5%			\$ 1,197.15
			<u>\$ 22,745.85</u>

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

			Estimated
No	Qty	Parts Description	Parts Price
36	1	Front right fender inner cowl	\$ 291.00x
37	1	Front bumper inner rubber	\$ 185.00x
38	1	Front bonnet side stand	\$ 176.00x
39	1	Front radar system assy	\$ 864.00x
40	1	Front turbo intercooler assy	\$ 1,421.00x
41	1	Front horn	\$ 121.00x
42	1	Front air con condenser assy	\$ 1,256.00x
43	1	Front radiator assy	\$ 1,455.00
44	1 set	Front radiator hoses	\$ 180.00
45	1	Front radiator fan motor assy	\$ 453.00
46	1	Front radiator fan cowl	\$ 321.00
			\$ 6,723.00
less 5%			\$ 336.15
			<u>\$ 6,386.85</u>

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

			Estimated
No.	Qty.	Parts Description	Parts Price
<u>Special Nett Items</u>			
1	1 set	Front M sport bumper clips	\$ 80.00 <i>30m -</i>
2	1 set	Front bumper lower grille clips	\$ 50.00 <i>lower</i>
3	1 set	Front centre kidney grille clips	\$ 50.00 <i>lower</i>
4	1	Front M sport bumper lower lip	\$ 1,400.00 <i>X M - 400</i>
5	1	Front no plate with garnish	\$ 100.00 <i>X</i>
6	1 set	Front right fender inner cowling clips	\$ 50.00 <i>X</i>
7	1 set	Front bumper right lower inner garnish clips	\$ 40.00 <i>X</i>
8	1 set	Front bumper left lower inner garnish clips	\$ 40.00 <i>X</i>
9	1 set	Front bumper centre lower inner garnish clips	\$ 40.00 <i>X</i>
10	1 set	Front kidney grille inner garnish clips	\$ 40.00 <i>X</i>
11	8	Front support panel top garnish clips (upper)	\$ 40.00 <i>X</i>
12	8	Front support panel top garnish clips (lower)	\$ 40.00 <i>X</i>
13	1	Front air con special gas	\$ 200.00 <i>X</i>
14	<i>2A</i>	Front parking sensor <i>@ \$200</i>	\$ 1,200.00 <i>nw ✓ 400</i>
15	2	Front radiator anti freeze coolant	\$ 200.00 <i>X</i>
			<u>\$ 3,570.00</u>
Total parts			\$ 32,702.70

26708.70

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,400.00 <i>400</i>
2	To putty and spray painting front portion.	\$ 1,400.00 <i>450</i>
3	To check wiring and focus front adaptive LED headlamp.	\$ 60.00 <i>30</i>
4	To remove and install front bonnet lock mechanism.	\$ 80.00 <i>X</i>
5	To apply anti rust proofing to front affected area.	\$ 140.00 <i>X</i>
6	To remove and install air con system to facilitate the repair and refill gas.	\$ 180.00 <i>X</i>
7	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 180.00 <i>X</i>
8	To remove and install front turbo intercooler assy.	\$ 180.00 <i>X</i>
9	Towing service.	\$ 100.00 <i>X</i>
Total labour :		\$ 3,720.00

Total parts : \$ 32,702.70

Total labour : \$ 3,720.00

Total repair cost : \$ 36,422.70

Tanjin 97495749
wp 12/6/22

L/s Mary after repair
tanjin@lkauto.com
~3 days

30428 n

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: