

(08/11/13)

REF

ASS. REC. BY:

CS/CT122007817/Tcy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 9MZ4623K Yr Regn: Apr / 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 2181 c.c. 1499Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 25515 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA12AK0707H58412Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NIL / S/Rim / STD A/Rim orTyre Size: F: 225 / 40 R 18

R: _____

BSY DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 12/8/22 D.O.I. 17/8/22

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
1/3/23	Finalised LS \$6500; 3 days with Ah Long. (Red: 23,928.20, 782)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 6500)

Fwd: BMW M218i Parts Prices

Simon Ho <simonhlc@yahoo.com>

Wed 22/2/2023 2:39 PM

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Sent from my iPhone

Begin forwarded message:

From:

Date: 22 February 2023 at 12:26:16 PM SGT

To:

Subject: BMW M218i Parts Prices

Parts Inquiry - Retail <<<			
FRONT GRILLE (LUXURY)			
PK SIZE: 1.00 PDC: D			
338 F44/M235i xDrive Gran C			
AIL Selling			
/	Price	Bin 1	Bin
0	301.75		

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

437E

			Estimated Parts Price	
No	Qty	Parts Description		
1	1	Front M sport bumper assy	\$	2,550.00 de - 951 + 40
2	2	Front bumper bracket	\$	128.00X
3	2	Front bumper side retainer	\$	✓138.00 KH de X
4	1	Front bumper centre kidney grille inner garnish	\$	395.00 X
5	1 set	Front bumper centre kidney grille	\$	893.00 cut - 301.75 + 80
6	1	Front bumper right outer cooling air duct	\$	226.00X
7	1	Front bumper left outer cooling air duct	\$	226.00X
8	1	Front intake top air duct	\$	350.00 cut - 122
9	1	Front bumper left side inner garnish	\$	129.00X
10	1	Front bumper right side inner garnish	\$	✓129.00 cut -
11	1	Front bumper lower grille	\$	589.00 cut - 177 + 50
12	1	Front bumper inner beam	\$	366.00X
13	1	Front bumper aluminium reinforcement	\$	678.00 bf - 412.80 + 70
14	1	Front bumper right lower inner garnish	\$	196.00X
15	1	Front bumper left lower inner garnish	\$	196.00X
16	1	Front bumper centre lower inner garnish	\$	229.00 cut -
17	1	Front bumper tow cover	\$	88.00 cut - 44
18	1	Front bonnet assy	\$	2,865.00
19	1 set	Front bonnet lock	\$	488.00
20	1 set	Front bonnet damper	\$	323.00
21	2	Front bonnet hinges	\$	160.00
22	1 set	Front bumper inner sponge	\$	180.00 cut -
23	1 set	Front bonnet rubber	\$	65.00
24	1	Front bumper centre logo	\$	✓108.00 cut -
25	1	Front support panel assy	\$	1,465.00 X
26	1	Front support panel top garnish (upper)	\$	156.00X
27	1	Front support panel top garnish (lower)	\$	156.00 X
28	1	Front support panel inner garnish	\$	275.00X
29	1	Front right adaptive LED headlamp	\$	4,886.00 cut - 2399.10 + 87
30	1	Front right adaptive LED headlamp module	\$	2,210.00 X
31	1	Front right headlamp support panel	\$	696.00 bf -
32	1	Front right LED lamp garnish	\$	148.00X
33	1	Front right LED lamp	\$	655.00 cut - 606.80
34	1	Front right fender	\$	1,481.00XR
35	1 set	Front right fender side bracket	\$	120.00 X
			\$	23,943.00
Less 5%			\$	1,197.15
			\$	22,745.85

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

			Estimated
No	Qty	Parts Description	Parts Price
36	1	Front right fender inner cowling	\$ 291.00X
37	1	Front bumper inner rubber	\$ 185.00X
38	1	Front bonnet side stand	\$ 176.00X
39	1	Front radar system assy	\$ 864.00X
40	1	Front turbo intercooler assy	\$ 1,421.00X
41	1	Front horn	\$ 121.00X
42	1	Front air con condenser assy	\$ 1,256.00X
43	1	Front radiator assy	\$ 1,455.00
44	1 set	Front radiator hoses	\$ 180.00
45	1	Front radiator fan motor assy	\$ 453.00
46	1	Front radiator fan cowling	\$ 321.00
			\$ 6,723.00
less 5%			\$ 336.15
			<u>\$ 6,386.85</u>

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

			Estimated
No	Qty	Parts Description	Parts Price
<u>Special Nett Items</u>			
1	1 set	Front M sport bumper clips	\$ 80.00 <i>30 net -</i>
2	1 set	Front bumper lower grille clips	\$ 50.00 <i>lower -</i>
3	1 set	Front centre kidney grille clips	\$ 50.00 <i>lower -</i>
4	1	Front M sport bumper lower lip	\$ 1,400.00 <i>K M - 400</i>
5	1	Front no plate with garnish	\$ 100.00 <i>X</i>
6	1 set	Front right fender inner cowling clips	\$ 50.00 <i>X</i>
7	1 set	Front bumper right lower inner garnish clips	\$ 40.00 <i>X</i>
8	1 set	Front bumper left lower inner garnish clips	\$ 40.00 <i>X</i>
9	1 set	Front bumper centre lower inner garnish clips	\$ 40.00 <i>X</i>
10	1 set	Front kidney grille inner garnish clips	\$ 40.00 <i>X</i>
11	8	Front support panel top garnish clips (upper)	\$ 40.00 <i>X</i>
12	8	Front support panel top garnish clips (lower)	\$ 40.00 <i>X</i>
13	1	Front air con special gas	\$ 200.00 <i>X</i>
14	<i>2A</i>	Front parking sensor <i>@ \$200</i>	\$ 1,200.00 <i>nw ✓ 400</i>
15	2	Front radiator anti freeze coolant	\$ 200.00 <i>X</i>
			<u>\$ 3,570.00</u>
Total parts			\$ 32,702.70

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,400.00 <i>400</i>
2	To putty and spray painting front portion.	\$ 1,400.00 <i>450</i>
3	To check wiring and focus front adaptive LED headlamp.	\$ 60.00 <i>30</i>
4	To remove and install front bonnet lock mechanism.	\$ 80.00 X
5	To apply anti rust proofing to front affected area.	\$ 140.00 X
6	To remove and install air con system to facilitate the repair and refill gas.	\$ 180.00 X
7	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 180.00 X
8	To remove and install front turbo intercooler assy.	\$ 180.00 X
9	Towing service.	\$ 100.00 X
Total labour :		\$ 3,720.00

Total parts : \$ 32,702.70

Total labour : \$ 3,720.00

Total repair cost : \$ 36,422.70 *30,428.20*

Tanpin 97495749
app 12/6/22
L/S Mury after repair
tanpin@lkkauto.com
~3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

437E

			Estimated Parts Price
			\$ 2,550.00 <i>de - 991</i>
1	1	Front M sport bumper assy	\$ 128.00 X
2	2	Front bumper bracket	\$ <i>✓</i> 138.00 <i>KH de X</i>
3	2	Front bumper side retainer	\$ 395.00 X
4	1	Front bumper centre kidney grille inner garnish	\$ 893.00 <i>cut - 381.75</i>
5	1 set	Front bumper centre kidney grille	\$ 226.00 X
6	1	Front bumper right outer cooling air duct	\$ 226.00 X
7	1	Front bumper left outer cooling air duct	\$ 350.00 <i>cm - 122</i>
8	1	Front intake top air duct	\$ 129.00 X
9	1	Front bumper left side inner garnish	\$ <i>✓</i> 129.00 <i>cut -</i>
10	1	Front bumper right side inner garnish	\$ 589.00 <i>cm - 227</i>
11	1	Front bumper lower grille	\$ 366.00 X
12	1	Front bumper inner beam	\$ 678.00 <i>bt - 482.80</i>
13	1	Front bumper aluminium reinforcement	\$ 196.00 X
14	1	Front bumper right lower inner garnish	\$ 196.00 X
15	1	Front bumper left lower inner garnish	\$ 229.00 <i>cm -</i>
16	1	Front bumper centre lower inner garnish	\$ 88.00 <i>cut - 44</i>
17	1	Front bumper tow cover	\$ 2,865.00
18	1	Front bonnet assy	\$ 488.00
19	1 set	Front bonnet lock	\$ 323.00
20	1 set	Front bonnet damper	\$ 160.00
21	2	Front bonnet hinges	\$ 180.00 <i>cm -</i>
22	1 set	Front bumper inner sponge	\$ 65.00
23	1 set	Front bonnet rubber	\$ <i>✓</i> 108.00 <i>cm -</i>
24	1	Front bumper centre logo	\$ 1,465.00 X
25	1	Front support panel assy	\$ 156.00 X
26	1	Front support panel top garnish (upper)	\$ 156.00 X
27	1	Front support panel top garnish (lower)	\$ 275.00 X
28	1	Front support panel inner garnish	\$ 4,886.00 <i>act - 2486.10</i>
29	1	Front right adaptive LED headlamp	\$ 2,210.00 X
30	1	Front right adaptive LED headlamp module	\$ 696.00 <i>bt -</i>
31	1	Front right headlamp support panel	\$ 148.00 X
32	1	Front right LED lamp garnish	\$ 655.00 <i>cm - 606.80</i>
33	1	Front right LED lamp	\$ 1,481.00 X R
34	1	Front right fender	\$ 120.00 X
35	1 set	Front right fender side bracket	\$ 23,943.00
Less 5%			\$ 1,197.15
			<u>\$ 22,745.85</u>

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

			Estimated
No	Qty	Parts Description	Parts Price
36	1	Front right fender inner cowling	\$ 291.00 X
37	1	Front bumper inner rubber	\$ 185.00 X
38	1	Front bonnet side stand	\$ 176.00 X
39	1	Front radar system assy	\$ 864.00 X
40	1	Front turbo intercooler assy	\$ 1,421.00 X
41	1	Front horn	\$ 121.00 X
42	1	Front air con condenser assy	\$ 1,256.00 X
43	1	Front radiator assy	\$ 1,455.00
44	1 set	Front radiator hoses	\$ 180.00
45	1	Front radiator fan motor assy	\$ 453.00
46	1	Front radiator fan cowling	\$ 321.00
			\$ 6,723.00
less 5%			\$ 336.15
			<u>\$ 6,386.85</u>

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

			Estimated
			Parts Price
No	Qty	Parts Description	
<u>Special Nett Items</u>			
1	1 set	Front M sport bumper clips	\$ 80.00 <i>30 net -</i>
2	1 set	Front bumper lower grille clips	\$ 50.00 <i>10 net -</i>
3	1 set	Front centre kidney grille clips	\$ 50.00 <i>10 net -</i>
4	1	Front M sport bumper lower lip	\$ 1,400.00 <i>X M - 400</i>
5	1	Front no plate with garnish	\$ 100.00 <i>X</i>
6	1 set	Front right fender inner cowlings clips	\$ 50.00 <i>X</i>
7	1 set	Front bumper right lower inner garnish clips	\$ 40.00 <i>X</i>
8	1 set	Front bumper left lower inner garnish clips	\$ 40.00 <i>X</i>
9	1 set	Front bumper centre lower inner garnish clips	\$ 40.00 <i>X</i>
10	1 set	Front kidney grille inner garnish clips	\$ 40.00 <i>X</i>
11	8	Front support panel top garnish clips (upper)	\$ 40.00 <i>X</i>
12	8	Front support panel top garnish clips (lower)	\$ 40.00 <i>X</i>
13	1	Front air con special gas	\$ 200.00 <i>X</i>
14	<i>2/4</i>	Front parking sensor <i>@\$200</i>	\$ 1,200.00 <i>1w ✓ 400</i>
15	2	Front radiator anti freeze coolant	\$ 200.00 <i>X</i>
			\$ 3,570.00
 Total parts			 \$ 32,702.70

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SMZ4623K M218i

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,400.00 400
2	To putty and spray painting front portion.	\$ 1,400.00 450
3	To check wiring and focus front adaptive LED headlamp.	\$ 60.00 30
4	To remove and install front bonnet lock mechanism.	\$ 80.00 X
5	To apply anti rust proofing to front affected area.	\$ 140.00 X
6	To remove and install air con system to facilitate the repair and refill gas.	\$ 180.00 X
7	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 180.00 X
8	To remove and install front turbo intercooler assy.	\$ 100.00 X
9	Towing service.	
Total labour :		\$ 3,720.00

Total parts : \$ 32,702.70

Total labour : \$ 3,720.00

Total repair cost : \$ 36,422.70

Tanpin 97495749
 -wp- 12/1/22

L/s Mrng after repair
 tanpin @ lkkauto.com
 ~3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: