


PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0701/2022/EQ
DATE : 16-Aug-22
WIP : 37551

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/08/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING


SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS TAI YIN LENG
ADDRESS : BLK 143 PASIR RIS GROVE
#10-60
SINGAPORE 518136
TELEPHONE : HP +65 97327446
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210078477-01
VEHICLE NO : SNA 9612 D
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 26/7/2021
ENGINE NO : CZD C40462
CHASSIS NO : WAUZZZF39M1120248
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Aug-22
PLACE OF ACCIDENT : STILL ROAD S

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 9612 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 /	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 ? /	
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00 ? /	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 ? /	
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00	2500 ✓ 2250
TOTAL LABOUR CHARGES		\$ 8,480.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NDRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 9612 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$ 2,500.00	11/99
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 11,172.00	

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 9612 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER (RH) / BR	1	\$	1,073.00 /	858.40
2	FRONT BUMPER CONNECTING PIECE ? X nn	1	\$	162.00	
3	FRONT BUMPER CLOSING ELEMENT - RH ? / BR	1	\$	66.00 /	52.32
4	FRONT BUMPER GRILLE - CENTER / BR	1	\$	242.00 /	193.60
5	FRONT BUMPER LOWER GRILLE COVER X nn	1	\$	58.00	
6	FRONT BUMPER GRILLE - RH / BR	1	\$	124.00 /	98.80
7	FRONT BUMPER CLOSING ELEMENT ? CRH	1	\$ X nn	212.00	
8	FRONT BUMPER SPOILER ? / CRH	1	\$	426.00 /	340.80
9	AIR GUIDE GRILLE - RH / MIS	1	\$	171.00 /	136.40
10	RADIATOR GRILLE / BR	1	\$	1,594.00 /	1275.20
11	FRONT STRIKER PLATE / BR	1	\$	271.00 /	216.80
12	FRONT S-LINE EMBLEM ? X nn	1	\$	47.00	
13	FRONT "360" CAMERA COVER CAP / BR	1	\$	46.00 /	36.88
14	FRONT "360" CAMERA BRACKET ? X nn	1	\$	37.00	
15	FRONT "360" CAMERA ? X nn	1	\$	1,264.00	
16	FRONT FOAM FILLER PIECE ? X nn	1	\$	114.00	
17	FRONT BUMPER CARRIER ? / BR	1	\$	974.00 /	778.80
18	FRONT BUMPER GUIDE SECTION - RH ? X nn	1	\$	43.00	
19	FRONT BUMPER TOP COVER / BR	1	\$	137.00 /	109.60
20	CAUTION SIGN STICKER / NA	1	\$	16.00 /	12.40
SUB TOTAL SPARE PARTS		:	\$	7,077.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 9612 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	AIR CONDITIONER STICKER / MC	1 S	9.00	/	6.64
22	FRONT PARKING AID SENSOR ? X MN	3 S	797.00		
23	FRONT PARKING AID SEAL RING X MC X MN	4 S	10.00		
24	FRONT BUMPER WIRING SET ? X MN	1 S	750.00		
25	FRONT FENDER - RH / DD	1 S	1,445.00	/	1156.00
26	FRONT FENDER ATTACHMENT PARTS X MN	1 S	66.00		
27	FRONT FENDER BRACE - RH ? X MN	1 S	98.00		
28	FRONT FENDER BRACKET - RH ? X MN	1 S	39.00		
29	FRONT FENDER CLOSING ELEMENT - RH ? X MN	1 S	37.00		
30	HEADLIGHT MOUNTING - LH / RH ? GR	22 S	264.00		210.40.
31	HEADLIGHT - RH ? CUT	1 S	5,952.00	/	4761.60
32	HEADLIGHT HOSE - RH ? X MN	1 S	28.00		
33	LIFT CYLINDER - RH / BR	1 S	231.00	/	184.40
34	LIFT CYLINDER HOSE ? X MN	1 S	92.00		
35	LOCK CARRIER ? / BR	1 S	1,412.00	/	1129.60
36	OUTSIDE TEMPERATURE SENSOR HOLDER ? X MN	1 S	9.00		
37	RADIATOR COOLANT ? / MC	6 S	297.00	/	237.12
38	AIR GUIDE - LH / RH ? / BR	2 S	86.00	/	34.08
39	AIR GUIDE - UPPER / LOWER ? / BR	12 S	96.00	/	37.84
40	FRONT WHEEL HOUSING LINER - RH ? X MN	1 S	260.00		
SUB TOTAL SPARE PARTS		:	\$	11,978.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 9612 D

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT FENDER COVER - RH X AN	1	\$	18.00	
42	FRONT WHEEL ARCH COVER - LH / RH / MC	(2)	\$	566.00	452.00
43	FRONT NO PLATE / BT	S/N	\$	60.00	60.00
44	SUNDRIES ? FREE X AN		\$	400.00	
TOTAL SPARE PARTS		:	\$	20,099.00	
TOTAL LABOUR CHARGES		:	\$	11,172.00	
GRAND TOTAL		:	\$	31,271.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408599
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Steve (LKR)
16/8/92 3:00p

00-M HL
EXHIB. C
P/P
My BL 4
J 45

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

[illegible]

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0701/2022/EQ

19-Aug-22

CHANG

1 of 1

SNA 9612 D

AUDI Q3 1.4 TFSI

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

1	A/C CONDENSER
---	---------------

1

\$ 605.00 ✓ DD 483.60

GRAND TOTAL

\$ 605.00

Steve (LKK) 25/08/22

Add 3 days (for replaced lock carrier)

For Premium Automobiles Pte Ltd



Authorised Signature