



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22007824/Ecy3e2 Date: 06/10/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 4929J	Veh. Inspected	SLK 7112P	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/08/22/2036	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	16/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6BN22A8H0136163	Colour	GREY	
Odometer	315696 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R15	DUNLOP	4 mm	
L/H Front Tyre	205/55 R15	DUNLOP	4 mm	
R/H Rear Tyre	205/55 R15	DUNLOP	4 mm	
L/H Rear Tyre	205/55 R15	DUNLOP	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/08/2022	Inspection Date	16/08/2022	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 74 Kian Teck Road Singapore 628800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	