

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 15-Aug-22

Estimate no.

1144

Plate No. FBL8873H

Model. HONDA FIGHAWK

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK ALIGNMENT <i>8?</i>	\$ 300.00		
2	HANDLE BAR <i>10?</i>	\$ 250.00		
3	HANDLE BAR END <i>X NV</i>	\$ 120.00		
4	MIRROR SET <i>Gar</i>	\$ 120.00		
5	HANDLE GUIDE <i>Cost</i>	\$ 150.00		
6	CRASH BAR <i>X Repair</i>	\$ 320.00		
7	REAR KEY LOCK <i>mis</i>	\$ 180.00		
8	REAR FAIRING COVER <i>CRK</i>	\$ 250.00		
9	REAR NUMBER PLATE <i>X Repair</i>	\$ 30.00		
10	REAR BOX <i>mis</i>	\$ 380.00		
11	FRONT LEFT FOOTREST <i>Cost</i>	\$ 150.00		
12	REAR LEFT FOOTREST <i>Cost</i>	\$ 120.00		
13	REAR SIGNAL LIGHT <i>Cost</i>	\$ 180.00		
14	LABOUR	\$ 500.00	<i>200.</i>	

2 Days.
 Comp sum repair
 After repair photos.
 Luo Qianf
 8288 0282
 16/8/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To return the vehicle to the repairer within 30 days.
- To provide a written report of the damage to the repairer.
- To provide a written report of the damage to the repairer.
- To provide a written report of the damage to the repairer.
- To provide a written report of the damage to the repairer.

Acknowledged by: _____

Signature: _____

Date: 16/8/2022

Less 10% \$

Sub Total : \$ 2,745.00

GST 7% \$ 192.15

Total: \$ 2,937.15

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.