

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO SHC1810L

12.08.2022

MAKE REG 13.09.2018

CHIANG/NTUC

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER X <i>Mar</i>		\$459.40
1	REAR BUMPER SIDE BRACKET RH X		\$55.80
1	REAR BUMPER REINFORCEMENT X		\$394.80
2	REAR BUMPER REINFORCEMENT LH/RH X		\$276.20
1	REAR BUMPER CENTRE MOULDING X		\$451.25
1	TOW COVER X		\$98.80
1	REAR FOG LAMP X		\$210.50
1	REAR NUMBER PLATE LAMP X		\$85.30
1	REAR BUMPER REFLECTOR LH/RH X		\$82.50
10	REAR BUMPER CLIPS X		\$22.00
	SUB TOTAL		\$2,136.55
	20.00%		\$427.31
	DISCOUNTED TOTAL		\$1,709.24
2	REAR FENDER ADVERTISEMENT X <i>cc</i>		\$100.00
1	REAR BUMPER MAT X <i>nn</i>		\$50.00
1	REAR NUMBER PLATE W/HOLDER X <i>at</i>		\$55.00
1	REAR REVERSE SENSOR X <i>nn</i>		\$180.00
			\$361.50
	Labour Charge		
	Panel Beating		\$600.00
	Spray Painting Charge		\$300.00
	Check Lighting and Wiring		\$60.00
	Tuff Coating		\$60.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$1,080.00
	ESTIMATE TOTAL		\$3,150.74
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

2 Days.
 4/5
 Gao Qian
 15/8/22
 qpm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before any painting
- To display damaged parts for survey
- Parts price must be on a "no bid" basis
- Third party survey on a "no bid" basis
- No illegal work
- Supplier must be approved and is signed by the Insurance Company

Acknowledged:
 Signature:
 Date: