

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC2528X
MAKE HYUNDAI
MODEL IONIQ

DATE: 15.08.22
MVA JUMANI
DOA: 14.08.22

NTUC (450m)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER ASSY X Repair			\$459.40
1	REAR BUMPER CENTRE MOULDING / ee			\$451.25
1	REAR BUMPER BEAM X Snn			\$394.80
10	REAR BUMPER CLIPS X			\$22.00
1	REAR FOG LAMP			\$201.50
1	ANTENNA - SMARTKEY ?			\$40.50
SUB TOTAL				\$1,569.45
LESS 20%				\$313.89
DISCOUNTED TOTAL				\$1,255.56
REVERSE SENSOR X nn				\$180.00
REAR NUMBER PLATE / Aut				\$50.00
				\$230.00
Labour Charge				
PANEL BEATING				\$400.00
SPRAY PAINT				\$300.00
REMOVE / REFIX REVERSE SENSOR				\$50.00
ADVERTISEMENT LOGO - FENDER = Snn				\$200.00
ADVERTISEMENT LOGO - BOOTLID				\$100.00
TOTAL LABOUR				\$1,050.00
ESTIMATE TOTAL				\$2,535.56

NET
NET

35c
25c
4c
=

28m9.
45

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Gno Q:ap
15/8/22
4pm

LKK Auto Consultants hence notify the Repairer of the following:

- To res...
- To dis...
- To res...
- To dis...

Third party... self basis
No...
Sur...
In... company