

REPAIR ESTIMATEDATE: **15.08.22**MODEL: **Hyundai Ioniq**INSURANCE: **NTUC CLS**VEHICLE NO.: **SHC8110C**MVA: **LIM T S**✓ Police Report
attached

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper / <i>cc</i>	1		\$ 459.40
	Rear Bumper Centre Moulding / <i>cc</i>	1		\$ 451.25
	Rear Bumper Cover Clips / <i>MS</i>	10	\$ 2.20	\$ 22.00
	Rear Bumper Reflector RH / LH X	2	\$ 41.45	\$ 82.90
	Rear Bumper Retainer RH / LH X	2	\$ 55.80	\$ 111.60
	Rear Bumper Fog Lamp / <i>Cut</i>	1		\$ 201.50
	Rear Bumper Smart Key Antenna ?	1		\$ 40.50
SUB TOTAL				\$ 1,369.15
LESS 20%				\$ 273.83
DISCOUNTED TOTAL				\$ 1,095.32
	Reverse Sensors / <i>PM</i>	1		\$ 180.00
	Rear No. Plate With Trim Cover / <i>MS</i>	1		\$ 55.00
SUB S/NETT				\$ 235.00
LESS 10%				\$ 23.50
S/NETT TOTAL				\$ 211.50
	Rear Fender Adv. Sticker RH/LH / <i>MS</i>	2	\$ 100.00	\$ 200.00
<u>Labour Charge</u>				
Panel Beating				\$ 400.00
Spray Painting Charge				\$ 300.00
Remove/Refix Reverse Sensor				\$ 120.00
TOTAL LABOUR				\$ 820.00
ESTIMATE TOTAL				\$ 2,326.82

350
250
40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.
45
Gang Giv
15/8/22
4pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display car for 24 hours for survey
- Parts provided for repair on "no dispute" basis
- Third party survey on "no dispute" basis
- No dispute on "no dispute" basis
- Supplier to provide parts and labour and is responsible for the repair work

Acknowledged:
Signature:
Date: