

TwinCar AUTOMOTIVE PTE LTD

Lee / Adrian

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

M&T AIR-CON ENGINEERING
BLK 429B YISHUN AVE 11 #05-360
SINGAPORE 762429

Contact : 90995442

TP Chiam.
Xiao Chen.

TAX INVOICE

Repair Code : CLM15620

Date in : 16/08/2022

Vehicle Num. : GBE345E

Model : TOYOTA HIACE 3.0 DX M

Chassis/Eng# : KDH2015018403/1KD2539758

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>New</i>	1	548.30	+ 548.30
FRONT BUMPER LH RETAINER <i>New</i>	1	142.80	+ 142.80
FRONT LH DOOR <i>Derbed</i>	1	1687.10	+ 1,687.10
FRONT LH DOOR ARCH SEAL RUBBER <i>New</i>	1	55.00	+ 55.00
FRONT LH DOOR GLASS <i>cut</i>	1	535.70	+ 535.70
FRONT LH DOOR GLASS CHANNEL SEAL <i>New</i>	1	133.60	+ 133.60
FRONT LH DOOR GLASS CHANNEL SEAL BRACKET <i>New</i>	1	72.00	+ 72.00
FRONT LH DOOR INNER PLASTIC SEAL COVER <i>New</i>	1	35.00	+ 35.00
FRONT LH DOOR MECHANISM LOCK <i>Derbed</i>	1	574.80	+ 574.80
FRONT LH DOOR OUTER HANDLE <i>cut</i>	1	188.10	+ 188.10
FRONT LH DOOR OUTER HANDLE KNOB COVER <i>cut</i>	1	18.10	+ 18.10
FRONT LH DOOR OUTER MOULDING <i>cut</i>	1	99.00	+ 99.00
FRONT LH DOOR RUBBER GUIDE STOPPER <i>New</i>	2	12.00	+ 24.00
FRONT LH DOOR SIDE MIRROR <i>Derbed</i>	1	1197.10	+ 1,197.10
FRONT LH DOOR WEATHER STRIP SEAL <i>cut</i>	1	230.10	+ 230.10
FRONT LH HEADLAMP <i>Derbed</i>	1	2584.50	+ 2,584.50
LH CENTER PILLAR <i>Derbed</i>	1	425.80	+ 425.80
LH SLIDING DOOR <i>Derbed</i>	1	1916.10	+ 1,916.10

1722

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

M&T AIR-CON ENGINEERING
BLK 429B YISHUN AVE 11 #05-360
SINGAPORE 762429

Contact : 90995442

TAX INVOICE

Repair Code : CLM15620

Date in : 16/08/2022

Vehicle Num. : GBE345E

Model : TOYOTA HIACE 3.0 DX M

Chassis/Eng# : KDH2015018403/1KD2539758

LH SLIDING DOOR OUTER HANDLE	1	188.10	✓	188.10
PETROL LID COVER	1	119.00	x	119.00
Subtotal before discount				10,774.20
Percentage discount 25%				2,693.55
Sub-total 1				8,080.65
FRONT BUMPER CLIPS - SET	1	50.00	+	50.00
FRONT LH DOOR COMPANY DETAIL STICKER	1	50.00	30	50.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	+	50.00
LH CENTER PILLAR SEALANT	1	100.00	50	100.00
LH SLIDING DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	+	50.00
Subtotal before discount				300.00
Percentage discount 0%				0.00
Sub-total 2				300.00
Parts-total				8,380.65

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)	30	60.00
To remove, reinstall petrol tank. (to FR)	x	100.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60.	120.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	80.	200.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

M&T AIR-CON ENGINEERING
BLK 429B YISHUN AVE 11 #05-360
SINGAPORE 762429

Contact : 90995442

TAX INVOICE

Repair Code : CLM15620

Date in : 16/08/2022

Vehicle Num. : GBE345E

Model : TOYOTA HIACE 3.0 DX M

Chassis/Eng# : KDH2015018403/1KD2539758

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

2,780.00

Parts & Labour Total

11,160.65

*** This is a computer-generated document which requires no signature.***

page 3

LK Auto Consultants hence notify the insurer of the following:

- Survey before/after spray painting
- Replace damaged part(s) during resurvey
- Prices are subject to confirmation
- Party survey is on a "Without Prejudice" basis
- Structural modification(s) is allowed
- Damaged item(s) must be resurveyed and subject to final approval from Insurance Company

Accepted by Repairer

Signature:

Adrian C
c/s 062yr.

Total: 66,088.82

c/s: S-2K

S-2K