

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial PK 2 Singapore 569541
 Tel : 64817221

Fax : 64816131

L H Car Rental Pte Ltd
 Blk 5038 #01-405
 Ang Mo Kio Industrial Pk 2
 Singapore 569541

*Not Notified
 11 Nov @ 1250p
 Missing After Paint
 3 days*

Vehicle No : SMM 4750 U
 Make/Model : Toyota Noah
 Year : 2019

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear tail-gate emblem " Hybrid "		<i>Na</i> \$65.10 ✓
1 pc	Rear tail-gate inner lock		<i>n</i> \$285.60 X
1 pc	Rear tail-gate inner lock sensor		<i>n</i> \$325.70 X
1 pc	Rear o/s tail-lamp lower garnish		<i>n</i> \$355.60 X
1 pc	Rear end panel		<i>n</i> \$650.10 X
1 pc	Rear bumper <i>1025.10</i>		<i>na</i> \$1,255.90 ✓
1 pc	Rear o/s bumper reflector		<i>na</i> \$105.10 X
1 pc	Rear o/s bumper side retainer <i>68.40</i>		<i>na</i> \$155.70 ✓
			\$3,198.80
Less 25 %			\$799.70
			\$2,399.10

S Nett

20 pcs	Rear bumper clip	\$2.00	<i>na</i> \$40.00 ✓
1 pc	Rear reverse sensor		<i>n</i> \$200.00 X

Labour charges

Remove/renew the above parts including knocking, welding & cutting.	\$500.00	<i>2500</i>
To putty and spray paint	\$800.00	<i>4000</i>
Check and reconnect wiring	\$40.00	<i>150</i>
Total	\$3,979.10	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: