

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 25 Aug 2022

**Preliminary Advice**

Insured : SLN143E  
Vehicle No  
TP Vehicle No : GBD8776Y  
Make : MITSUBISHI CANTER  
Date of Inspection : 17/08/2022  
Inspection At : LIU'S BROTHER AUTO WORKSHOP (HQ)  
1 KAKI BUKIT AVE 6 #01-01, AUTO BAY@KAKI BUKIT  
SINGAPORE 417883

Accident Date : 13/08/2022  
Assignment Date : 17/08/2022  
Est. Duration of Repair : 3

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,545.80
Revised Amount	:S\$	2,632.30
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,632.30

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

**Remarks**

( ) The vehicle is economical for repair

( ) The vehicle is not economical for repair

( ) Part-by-Part repair

( X ) Lump Sum repair

( X ) The above survey was conducted on a 'without prejudice' basis.  
Please note that the preliminary advice amount (Revised & Check Items)  
stated are subject to consistency check, part prices and labour cost.