



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|------------------------|--|-----------|
| AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 | | | Ref: CS/AGI22007862/Uny3q2 Date: 05/10/2022 | Code: AGI |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SGS 9990A | Veh. Inspected | SNF 8886K | |
| Policy No. | P10340172R02 | Coverage (\$) | 0.00 | |
| Claim No. | C10016937/JY | Excess (\$) | 0.00 | |
| Assign From | SALIZAWATI | Assign Date | 17/08/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | MINI COOPER S HB (A) | c.c | 1598 | |
| Engine No. | HIDDEN | Year of Reg. | 2010 | |
| Chassis No. | WMWSV32070TY82269 | Colour | WHITE | |
| Odometer | 145424 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 215/45 R17 | MICHELIN | 6 mm | |
| L/H Front Tyre | 215/45 R17 | MICHELIN | 6 mm | |
| R/H Rear Tyre | 215/45 R17 | MICHELIN | 6 mm | |
| L/H Rear Tyre | 215/45 R17 | MICHELIN | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 15/08/2022 | Inspection Date | 17/08/2022 | |
| Survey held at | ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 4 Working Days | |