



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD
6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Ref: CS3/FWD22007864/Rvy3

Date: 17/08/2022

Code: FWD

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SML 5308M	Veh. Inspected	SLA 9200H
Policy No.		Coverage (\$)	0.00
Claim No.	1202200025500-002/EC	Excess (\$)	0.00
Assign From	ELAINE CHEONG	Assign Date	17/08/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	15/08/2022	Inspection Date	19/08/2022
Survey held at	PERFECT POWER PTE LTD 1 BUKIT BATOK CRESCENT #06-12, WCEGA PLAZA SINGAPORE 658064		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.