



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22007869/Tcy3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 29/09/2022

ATTN: RODERIC YUEN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 3650Z	Veh. Inspected	GX 8202Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1184157-002	Excess (\$)	0.00
Assign From	DIANA TAY	Assign Date	17/08/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA LITEACE 2.2M	c.c	2184
Engine No.	HIDDEN	Year of Reg.	2004
Chassis No.	CR425009847	Colour	WHITE
Odometer	549878 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	MICHELIN	6 mm
L/H Front Tyre	185/70 R14	MICHELIN	6 mm
R/H Rear Tyre	185/70 R14	MICHELIN	6 mm
L/H Rear Tyre	185/70 R14	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/08/2022	Inspect Date / Time	17/08/2022 (11:15 AM)
Survey held at	AUTO BUDDY 60D KALLANG PUDDING ROAD #01-02 INGOLSTADT CENTRE SINGAPORE 349321		

5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------