



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 8192H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	LEFT REAR TAIL LIGHT (N)	CRACKED	684.00	684.00
4	LEFT REAR TAIL LIGHT CLIPS @\$5.50 (N)	NECESSARY	22.00	22.00
1	LEFT REAR BOOT REFLECTOR (N)	NOT NECESSARY	345.00	-
1	REAR BUMPER (N)	DEFORMED	1,558.00	1,558.00
1	REAR BUMPER REINFORCEMENT (N)	NOT NECESSARY	485.00	-
1	REAR BUMPER FOAM (N)	NOT NECESSARY	145.00	-
1	SET REAR BUMPER CLIPS (N)	NECESSARY	68.00	30.00
2	REAR BUMPER SIDE RETAINERS @\$52.00 (N)	N/S DAMAGED	104.00	52.00
1	LEFT REAR BUMPER CHROME MOULDING (N)	NECESSARY	168.00	168.00
2	LEFT REAR BUMPER SENSORS @\$245.00 (N)	DAMAGED (1 PCS ONLY)	490.00	245.00
2	LEFT REAR BUMPER SENSOR COVERS @\$18.00	NECESSARY	36.00	36.00
1	LEFT REAR BUMPER INNER MOUNTING (N) (ADDITIONAL)	BROKEN	72.00	72.00
1	REAR BUMPER INNER CENTRE GARNISH (N) (ADDITIONAL)	BROKEN	94.00	94.00
10	REAR BUMPER CENTRE GARNISH RIVETS @\$5.50 (N) (ADDITIONAL)	NECESSARY	55.00	30.00
	LESS 10% DISCOUNT		-432.60	-299.10
			3,893.40	2,691.90
	<b><u>LABOUR</u></b>			
	TO KNOCK ,STRAIGHTEN REAR SUPPORT PANEL,LEFT REAR FENDER ,REAR INNER PANEL,REAR LOWER PANEL ,REAR SIDE PANEL ,RENEW REAR LIGHT ,REAR REFLECTOR ,REAR BUMPER AND ASSEMBLY.		800.00	550.00
	TO RESPRAY DAMAGED PARTS (BUMPER ,L/R FENDER ,END PANEL).		800.00	700.00
	TO REMOVE REAR GARNISHES ,CARPET ,UPHOLSTERY TO FACILITATE REPAIRS AND ASSEMBLY.	NOT NECESSARY	120.00	-
	TO RESEAL JOINTS ,REINSULATE ,ANTI RUST PANELS AND ASSEMBLY.		80.00	30.00
	TO CHECK AND RESET ECU.		150.00	100.00
			1,950.00	1,380.00
	<b>GRAND TOTAL</b>		<b>5,843.40</b>	<b>4,071.90</b>

Report Ref No. CS/SMO22007873/Acy3e2



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,250.00</b>
---	--	--	-----------------

Report Ref No. CS/SMO22007873/Acy3e2

**ADRIAN LING WAI PING**

**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**