



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22007873/Acy3e2	
			Date: 02/12/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GV 4804Y	Veh. Inspected	SKL 8192H	
Policy No.	D22MPTCVE001454	Coverage (\$)	0.00	
Claim No.	CMTD2202796/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	17/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E250	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	WDD2120362A873705	Colour	GREY	
Odometer	155684 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	265/35 R18	CONTINENTAL	6 mm	
L/H Front Tyre	265/35 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	265/35 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	265/35 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/08/2022	Inspection Date	22/08/2022	
Survey held at	SHU FATT AUTO WORKS BLK 1009, BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	