



樹發汽車修理廠 SHU FATT AUTO WORKS

0-71

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref: WSK/jw/SF-que

15th August 2022

TP Somp

SKL 8192 H MERCEDES BENZ E250

		SS		
Spare Parts	1	Left rear tail light.	684.00	Nett ✓
	4	Left rear tail light clips. @\$5.50	22.00	Nett ✓
	1	Left rear boot reflector.	345.00	Nett ✓
	1	Rear bumper.	1558.00	Nett ✓
	1	Rear bumper reinforcement.	485.00	Nett ✓
	1	Rear bumper foam.	145.00	Nett ✓
	1	Set rear bumper clips.	68.00	Nett 30.
	2	Rear bumper side retainers. @\$52/-	104.00	Nett 52.
	1	Left rear bumper chrome moulding.	168.00	Nett ✓
	2	Left rear bumper sensors. @\$245/-	490.00	Nett 245
	2	Left rear bumper sensor covers. @\$18/-	36.00	Nett ✓
			4105.00	
		Less 10%	410.50	
			3694.50	
Labour	To knock, straighten rear support panel, left rear fender, rear inner panel, rear lower panel, rear side pnael, renew rear light, rear reflector, rear bumper and assembly. ✓		800.00	550
	To respray damaged parts. bumper, rear fender, end panel		800.00	700
	To remove rear garnishes, carpets, upholstery to facilitate repairs and assembly.		120.00	✓
	To reseal joints, reinsulate, anti rust panels and assembly.		80.00	30.
	To check and reset ECU.		150.00	100
			5644.50	5865.50

Continental 265/35R18
WDD2120362A873705
155397

Adrian Lj. HKK
2/S 22/08/22

04 Days.

96893735.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: