



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref: WSK/jw SF-que

15th August 2022

TP Sempu

leaving for holiday on 9/9/22

Returning 22/9/22

Conny - Gee Yang

SKL 8192 H MERCEDES BENZ E250

Spare Parts	1	Left rear tail light	ouch d	SS	684.00	Nett	✓
	4	Left rear tail light clips	@\$5.50	by 21/9/22	22.00	Nett	✓
	1	Left rear boot reflector	Abel m		345.00	Nett	+
	1	Rear bumper	ouch d	6/9/22	1558.00	Nett	✓
	1	Rear bumper reinforcement	ouch d		485.00	Nett	+
	1	Rear bumper foam	ouch d		145.00	Nett	+
	1	Set rear bumper clips	ouch d		68.00	Nett	30
	2	Rear bumper side retainers	@\$52 - LH Rnd		104.00	Nett	52
	1	Left rear bumper chrome moulding	ouch d		168.00	Nett	✓
	2	Left rear bumper sensors	@\$245 - 1 piece dmd		490.00	Nett	245
	2	Left rear bumper sensor covers	@\$18 - ouch d		36.00	Nett	✓
					4105.00		
					Less 10%	410.50	
					3694.50		
Labour		To knock, straighten rear support panel, left rear fender, rear inner panel, rear lower panel, rear side panel, renew rear light, rear reflector, rear bumper and assembly.			800.00	280 - 760	550 ✓
		To respray damaged parts, bumper, V2 fender, end panel			800.00	280 - 720	✓
		To remove rear garnishes, carpets, upholstery to facilitate repairs and assembly.			120.00	+	
		To reseal joints, reinsulate, anti rust panels and assembly.			80.00	30	
		To check and reset ECU			150.00	100	
					5644.50		

Continental 265 35R18
WDD2120362A873705
155397

Steve (LKK)

18/9/22

Adrian Lj. HK
2/S 22/08/22

03 Days. ✓

96893735

27/9: car in 27/9/2022

1:15pm

28/9: Called Adrian for enquiry.



樹發汽車修理廠
SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Email: shufatt@pacific.net.sg

Co. Reg. No. 09062400M GST Reg. No. 09-062400-M

Our Ref: WSK/jw/SF-quo
15th August 2022

Supplementary

Sompo Insurance Singapore Pte Ltd
(Third Party)

SKL 8192 H MERCEDES BENZ E250

Spare Parts	1	Left rear bumper inner mounting	/ GR	SS	72.00	nett
	1	Rear bumper inner centre garnish	/ GR		94.00	nett

					166.00	

Steve (LKK)
28/9/22