

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

TP Chim
venn
M2053HY9305098459

SJN1210L Toyota Vios

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>Dislhd</i>	\$ 589.30 ✓
2	2	Rear bumper bracket <i>Dislhd</i>	\$ 89.80 ✓
3	2	Rear bumper side retainer <i>Dislhd</i>	\$ 88.80 ✓
4	2	Rear bumper lower reflector <i>Dislhd</i>	\$ 128.60 ✓
5	1	Rear bootlid assy <i>Dislhd</i>	\$ 771.40 ✓
6	1	Rear bootlid weatherstrip <i>Dislhd</i>	\$ 168.70 ✓
7	1	Rear bootlid lock <i>Dislhd</i>	\$ 165.90 ✓
8	1	Rear bootlid lock cylinder <i>Dislhd</i>	\$ 195.10 ✓
9	1	Rear bootlid lock catch <i>Dislhd</i>	\$ 62.40 ✓
10	1	Rear bootlid outer garnish <i>Dislhd</i>	\$ 172.80 ✓
11	2	Rear bootlid number plate lamps <i>Dislhd</i>	\$ 120.10 ✓
12	1	Rear bootlid centre logo <i>Dislhd</i>	\$ 68.30 ✓
13	1	Rear bootlid 'E' emblem <i>Dislhd</i>	\$ 64.30 ✓
14	1	Rear bootlid 'Vios' emblem <i>Dislhd</i>	\$ 68.80 ✓
15	1 set	Rear bootlid rubber stopper <i>Dislhd</i>	\$ 48.60 ✓
16	2	Rear bootlid hinges <i>Dislhd</i>	\$ 145.50 ✓
17	1	Rear right fender <i>Dislhd</i>	\$ 992.40 ✓
18	1	Rear left fender <i>Dislhd</i>	\$ 992.40 ✓
19	1	Rear left fender inner side garnish <i>Dislhd</i>	\$ 379.40 ✓ 285
20	1	Rear right fender inner side garnish <i>Dislhd</i>	\$ 379.40 ✓ 285
21	1	Rear left fender inner cowlings <i>Dislhd</i>	\$ 146.20 ✓
22	1	Rear right fender inner cowlings <i>Dislhd</i>	\$ 146.20 ✓
23	1	Rear left taillamp <i>Dislhd</i>	\$ 457.80 ✓ 345
24	1	Rear right taillamp <i>Dislhd</i>	\$ 457.80 ✓ 345
25	1	Rear left taillamp lower bracket <i>Dislhd</i>	\$ 26.30 ✓
26	1	Rear right taillamp lower bracket <i>Dislhd</i>	\$ 26.30 ✓
27	1	Rear end panel <i>Dislhd</i>	\$ 864.80 ✓ 660
28	1	Rear end panel top garnish <i>Dislhd</i>	\$ 96.20 ✓
29	1	Rear floor panel <i>Dislhd</i>	\$ 972.10 ✓
30	1	Spare tyre top carpet <i>Dislhd</i>	\$ 228.50 ✓
31	2	Spare tyre top side sponge <i>Dislhd</i>	\$ 220.80 ✓
32	1	Spare tyre top board <i>Dislhd</i>	\$ 152.70 ✓
33	1	Rear exhaust muffler assy <i>Dislhd</i>	\$ 987.90 ✓
34	2	Rear exhaust muffler rubber mounting <i>Dislhd</i>	\$ 66.10 ✓
35	1	Rear windscreen glass moulding <i>Dislhd</i>	\$ 166.10 ✓
			\$ 10,707.80
less 25%			\$ 2,676.95
			\$ 8,030.85

6429.10
4821.82

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJN1210L Toyota Vios

			Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips <i>new</i>	\$ 60.00 30
2	4	Rear end panel top garnish clips <i>new</i>	\$ 30.00 10
3	1	Rear end panel sealant <i>new</i>	\$ 140.00 60
4	2	Rear bumper reverse sensor <i>2 pin</i>	\$ 300.00 20
5	1	Rear left fender sealant <i>new</i>	\$ 100.00 60
6	1	Rear right fender sealant <i>new</i>	\$ 100.00 *
7	4	Rear left fender inner cowling clips <i>green</i>	\$ 30.00 *
8	4	Rear right fender inner cowling clips <i>green</i>	\$ 30.00 *
9	6	Rear left fender inner side garnish clips <i>new</i>	\$ 40.00 2 30
10	6	Rear right fender inner side garnish clips <i>new</i>	\$ 40.00 2 30
11	1	Rear no plate <i>best</i>	\$ 100.00 60
12	4	Rear bootlid outer garnish clips <i>new</i>	\$ 30.00 10
13	1	Rear windscreen glass sealant <i>new</i>	\$ 100.00 60
14	1	Rear floor panel sealant <i>green</i>	\$ 150.00 *
15	1	Rear floor panel insulator pad <i>green</i>	\$ 180.00 *
			\$ 1,430.00
Total parts			\$ 9,460.85

550

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJN1210L Toyota Vios

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts including floor panel.	\$ 1,400.00 1300
2	To putty and spray painting rear portion.	\$ 1,400.00 1300
3	To check rear lighting and wiring.	\$ 50.00 30
4	To remove and install rear bootlid lock mechanism.	\$ 80.00 60
5	To remove and install rear exhaust muffler assy.	\$ 120.00 80
6	To remove and install rear fuel tank to facilitate the repair.	\$ 180.00 80
7	To remove and install rear inner garnish and trim to facilitate the repair.	\$ 180.00 80
8	To apply anti rust proofing to rear affected area.	\$ 140.00 100
9	To remove and install rear bumper reverse sensor.	\$ 80.00 50
10	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 120
11	Towing accident vehicle to workshop.	\$ 100.00 60
12	To repair straighten and align both rear door panel assy.	\$ 350.00 *
13	To conduct chassis alignment.	\$ 350.00 +.
Total labour :		\$ 4,570.00

3260

Total parts : \$ 9,460.85
Total labour : \$ 4,570.00
Total repair cost : \$ 14,030.85

16,440.95

Adrian Lj
 L/S 16/08/22.
 10 Days.

Supplementary: 1373

Total: 10004.82

L/S: 8k

8k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJN1210L Toyota Vios- Supplementary Items

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear windscreen glass assy <i>at.</i>	\$ 1,410.10 <i>980</i>
2	1	Rear windscreen glass moulding <i>Replaced</i>	\$ 166.10 <i>252</i>
3	1	Rear left taillamp lower panel <i>Replaced</i>	\$ 485.30 <i>252</i>
4	1	Rear right taillamp lower panel	\$ 485.30
			\$ 2,546.80
		less 25%	\$ 636.70
			\$ 1,910.10

Special Nett Items

1	1	Rear windscreen glass sealant <i>3m</i>	\$ 100.00 <i>40</i>
2	1	Rear windscreen glass seal <i>3m</i>	\$ 100.00 <i>40</i>
3	1	Rear left taillamp lower panel sealant <i>3m</i>	\$ 80.00 <i>30</i>
4	1	Rear right taillamp lower panel sealant <i>3m</i>	\$ 80.00 <i>30</i>
			\$ 360.00

Total parts

\$ 2,270.10

No	Item	Description	Labour Charges
1	1	To remove and install rear windscreen glass to facilitate the repair.	\$ 140.00 <i>120</i>

Total labour

\$ 140.00

Total repair cost

\$ 2,410.10

Supplementary: 1373.