

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLT77566R
 at Workshop m/s: JMK
 of _____
 Insured: SLU32875
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$64k.
 IDAC Accident Rport: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: LIA\$29445
 Vehicle: IN / OUT

Veh No: SLT7566R Yr Regn: 09/11/17
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA/
 Make: Honda Vezel Hybrid 1496
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp.Reading: 75722 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RU31258697
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/60R16
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MICY OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal. mm R/Bal. mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 15/08/22 D.O.I. 18/08/22
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/8/22	Have a/c 1/5 \$6200 insured sumins (red to 5478.88), 47%

Date/Time, File Pass to?
 1) 24/8/22: Preli. Report
 Date/Time, File Return to?
 2) _____: Final Report

Days Of Repair: 5
 Resurvey No. of Trip: 2

Survey Fee:	
Transportation:	
_____ S + RS, ___ SI	
Photos	
Others	
TOTAL	

Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Invs (\$)
 Weekend (\$)

Report Format: TP
 Lump Sum / I.B.1: (\$ 6200)

NOT Authorised
 on
 mercury
 18/08/22 L/S \$6200 /
 5 days

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: Fiona Sim Siew Tse
 3RD PARTY INSURER: Auto & General Insurance
 DOA: 15/08/2022

REPAIR ESTIMATE

Est No. : EST22080205
 Date : 16 Aug 2022
 Vehicle Num : SLT7566R
 Make/Model : Honda Vezel HYBRID 1.5X
 Chassis # : RU31258697
 Engine # : LEB5958715
 Yr. Of Manu : 2017

No.	Description	Qty	U/P	Amt	
Section: LIST ITEMS					
1	Rear Bumper 762.00	Dis	1.00	929.60	929.60 ✓
2	Rear Bumper Retainer LH/RH	Set	2.00	27.50	55.00 ✓
3	Rear Bumper Clips	ner	10.00	5.00	50.00 ✓
4	Rear Bumper Reflector LH/RH	11	2.00	270.80	541.60 X
5	Rear Bumper Lower Cover	11	1.00	292.10	292.10 ✓
6	Tailgate 1099.20	Body	1.00	1250.20	1250.20 ✓
7	Tailgate Lock 180.20	Set/11	1.00	356.10	356.10 ✓
8	Tailgate Lock Catch	11	1.00	66.40	66.40 X
9	Tailgate "VEZEL" Emblem	ner	1.00	63.20	63.20 ✓
10	Tailgate "HYBRID" Emblem	ner	1.00	80.50	80.50 ✓
11	Tailgate "LOGO" Emblem	ner	1.00	38.70	38.70 ✓
12	Tailgate Lamp LH/RH 340.80 x 2 = 681	CR	2.00	524.60	1049.20 ✓
13	Taillamp LH/RH	CR	2.00	586.70	1173.40 ✓
14	Tailgate Wiper Blade	11	1.00	78.60	78.60 X
15	Tailgate Wiper Blade Arm	11	1.00	101.20	101.20 X
16	Tailgate Wiper Motor	11	1.00	305.10	305.10 X
17	Tailgate Windscreen Moulding	11	1.00	136.80	136.80 ✓
18	Tailgate Inner Trim Board	Set/11	1.00	285.20	285.20 ✓
19	Tailgate Garnish	CR	1.00	289.50	289.50 ✓
20	Tailgate Rubber	11	1.00	185.20	185.20 ✓
21	Rear Number Plate Lamp LH/RH	11	2.00	68.50	137.00 X
22	Rear Bumper Corner Panel LH/RH	2e	2.00	272.80	545.60 ✓
23	Rear End Panel 517.30	Body	1.00	638.20	638.20 ✓

Continue on next page...



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER: Fiona Sim Siew Tse
3RD PARTY INSURER: Auto & General Insurance
DOA: 15/08/2022

REPAIR ESTIMATE

Est No. : EST22080205
Date : 16 Aug 2022
Vehicle Num : SLT7566R
Make/Model : Honda Vezel HYBRID 1.5X
Chassis # : RU31258697
Engine # : LEB5958715
Yr. Of Manu : 2017

No.	Description	Qty	U/P	Amt
Section: LIST ITEMS				
24	Rear End Panel Top Garnish	1.00	148.20	148.20
25	Rear Reverse Sensor	2.00	310.20	620.40
26	Rear Antenna Sensor	1.00	128.10	128.10
27	Rear Spare Tyre Panel	1.00	887.50	887.50
28	Rear Spare Tyre Top Board	1.00	559.60	559.60
29	Rear Spare Tyre Panel Sponge	1.00	343.90	343.90
				Amt S\$ 11336.10
				Discount (20.00%) S\$ 2267.22
				Subtotal S\$ 9068.88

Section: SPECIAL NETT ITEMS				
30	Rear Number Plate With Cover	1.00	50.00	50.00
				Amt S\$ 50.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 50.00

Continue on next page...



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER: Fiona Sim Siew Tse
3RD PARTY INSURER: Auto & General Insurance
DOA: 15/08/2022

REPAIR ESTIMATE

Est No. : EST22080205
Date : 16/Aug/22
Vehicle Num : SLT7566R
Make/Model : Honda Vezel HYBRID 1.5X
Chassis # : RU31258697
Engine # : LEB5958715
Yr. Of Manu : 2017

No.	Description	Qty	U/P	Amt
Section: LABOUR				
34	To Panel Beat and Renewal Of All Necessary Damaged Parts	1.00	1080.00	1080.00 <i>850</i>
35	To Sand Down, Putty and Spray Paint on Necessary Damaged Parts	1.00	1180.00	1180.00 <i>1000</i>
36	To Check All Wiring	1.00	50.00	50.00 <i>20</i>
37	To Dismantle & Reinstall Rear Windscreen To Facilitate Repair	1.00	200.00	200.00 <i>120</i>
38	To Remove & Replace Rear Reverse Sensor	1.00	50.00	50.00 <i>✓</i>
				Amt S\$ 2560.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 2560.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s), during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*2-6864.50
20%*
2-5491.60
S.N-240
2-2040
7771.60
20%
6217.28



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 9068.88
SPECIAL NETT ITEMS Subtotal S\$ 50.00
LABOUR Subtotal S\$ 2560.00
Total S\$ 11678.88

