

Engineering Pte Ltd (Co. Reg No. 199506048W)
05 Braddell Road
Singapore 579701
/67/65462533 Email: teokeejin@cdge.com.sg

e Pte Ltd (HQ)

Damage)

4

6T

MM

JLVO S60, 1.5 T2 (A)

rey

B4154T52283474

49286 KM

Ref. No:

Date of Loss: 08/08/2022

Driveable?

Party At Fault: UNKNOWN

Third Party Involved? YES

Contact No: +6596613829

Vehicle Reg. Date: 28/12/2017

Chassis No: YV1FS28L0J2456855

IO

5dys

8758ch

Not Notified
Runny B4 pain
Ex 8775h

COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

6,468.00

0.00

2,010.00

0.00

0.00

Gross Total (S\$)

8,478.00

+ GST 7.00% (S\$)

593.46

Nett Amount (S\$)

9,071.46

led by: PATRICK TIA JEE KIANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

149

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Aug 2022)
 Parts: 143 VOLVO S60 1.5 T2 (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SJJ2606T/17/08/2022 08:54
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT RH DOOR WING MIRROR ASSEMBLY	0.00	0.00	*950.00 F
2	1		*FRT RH DOOR WING MIRROR	0.00	0.00	*340.00 F
3	1		*FRT RH DOOR	0.00	0.00	*2,850.00 F
4	1		*FRT RH DOOR GLASS	0.00	0.00	*630.00 F
5	1		*FRT RH DOOR FRAME MOULDING CHROME	0.00	0.00	*450.00 F
6	1		*FRT RH DOOR GLASS MOULDING	0.00	0.00	*330.00 F
7	1		*RH ROCKER PANEL GARNISH	0.00	0.00	*330.00 F
8	1		*FRT RH FENDER (REPAIR)	0.00	0.00	*-F
9	1		*FRT RH WHEEL RIM (REPAIR)	0.00	0.00	*-F
10	1		*REAR RH DOOR (REPAIR)	0.00	0.00	*-F
11	1		*REAR RH FENDER (REPAIR)	0.00	0.00	*-F
12	1		*REAR RH WHEEL RIM (REPAIR)	0.00	0.00	*-F

F=Franchise part.

Sub Total (\$\$) 5,880.00
 + Margin on L,N Items 10.00% (\$\$) 588.00
 Total Parts (\$\$) 6,468.00

ComfortDelGro Engineering Pte Ltd/SJJ2606T/17/08/2022 08:54. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Supr

FRT RH Door Wing Mirror Cover. \$170

mi

pd

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK & STRAIGHTEN ON ACCIDENT AREA, TO REMOVE & REFIT RIGHT DAMAGE PARTS	New	600.00
2	TO PUTTY & RESPRAY ON RIGHT SIDE AFFECTED AREA	New	1,000.00
3	TO REPAIR & RESPRAY FRT RIGHT WHEEL RIM, REAR RIGHT WHEEL RIM	New	200.00
4	TO CHECK WIRING	New	50.00
5	TO DO WHEEL ALIGNMENT	New	80.00
6	TO REMOVE & REFIT DOOR TRIM, DOOR GLASS, WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD	New	80.00
Gross Labour Cost (S\$)			2,010.00

ComfortDelGro Engineering Pte Ltd/SJJ2606T/17/08/2022 08:54. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5,430
 170
 5,600
 + 10%
 P 6,160
 L 1,420
 7,580.00 ✓ ok

P/P
 \$7,580
 5 days