



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: CYNTHIA		Ref: CC4/ASM22007882/Epa3q2 Date: 05/07/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJK 2185K	Veh. Inspected	XE 2674G
Policy No.	P2382948	Coverage (\$)	0.00
Claim No.	S2M047U4	Excess (\$)	0.00
Assign From		Assign Date	17/08/2022
2. Vehicle Particulars & Condition			
Make & Model	SCANIA P360	c.c	12742
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	YS2P6X40005444447	Colour	MULTI COLOUR
Odometer	340470 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	FIRENZA	5 mm
L/H Front Tyre	295/80 R22.5	FIRENZA	5 mm
R/H Rear Tyre	295/80 R22.5	FIRENZA	5 mm
L/H Rear Tyre	295/80 R22.5	FIRENZA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/07/2022	Inspection Date	04/10/2022
Survey held at	SIN SHENG AUTO WORKSHOP PTE LTD 5 TUAS AVENUE 3, SINGAPORE 639405		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	