

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MAHA BODHI SCHOOL BUS SERVICE
 BLK 63 CHAI CHEE ROAD #11-808
 SINGAPORE 460063

Contact : 96625022

TP Allianz.
 Cecilia.

TAX INVOICE

Repair Code : CLM17332
 Date in : 11/08/2022
 Vehicle Num. : CB8448T
 Model : TOYOTA HIACE 3.0 DX DIESEL TURBO AT 2WD
 Chassis/Eng# : KDH2010232268/1KD2746924

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>dent</i>	1	706.00	✓ 706.00
REAR BUMPER LOWER BRACKET <i>2 pieces bent</i>	4	45.10	80.20 180.40
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	66.10	✓ 132.20
REAR BUMPER STEP BRACKET <i>Dented</i>	1	299.80	✓ 299.80
REAR END PANEL (INNER) <i>Repair</i>	1	926.50	+ 926.50
REAR END PANEL (OUTER) <i>Dented</i>	1	563.00	✓ 563.00
REAR END PANEL SIDE RUBBER STOPPER L/R <i>new</i>	2	68.10	+ 136.20
REAR END PANEL TOP MOULDING <i>new</i>	1	198.10	+ 198.10
REAR LH TAILLAMP <i>crack</i>	1	354.80	✓ 354.80
REAR LH TAILLAMP LOWER GARNISH <i>Repair</i>	1	157.00	+ 157.00
REAR SPARE TYRE CARRIAGE BRACKET <i>Best</i>	1	243.10	✓ 243.10
REAR TAILGATE <i>Dented</i>	1	1950.00	✓ 1,950.00
REAR TAILGATE 'LOGO' EMBLEM <i>2 pieces</i>	1	71.60	✓ 71.60
REAR TAILGATE 'TOYOTA HIACE' STICKER	1	58.00	✓ 58.00
REAR TAILGATE DUST SEAL COVER <i>new</i>	2	21.70	+ 43.40
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>new</i>	2	28.50	+ 57.00
REAR TAILGATE LOCK STRIKER <i>new</i>	1	70.20	+ 70.20
REAR TAILGATE LOWER JOINT MOULDING L/R <i>new</i>	2	21.60	+ 43.20

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MAHA BODHI SCHOOL BUS SERVICE
 BLK 63 CHAI CHEE ROAD #11-808
 SINGAPORE 460063

Contact : 96625022

TAX INVOICE

Repair Code : CLM17332
 Date in : 11/08/2022
 Vehicle Num. : CB8448T
 Model : TOYOTA HIACE 3.0 DX DIESEL TURBO AT 2WD
 Chassis/Eng# : KDH2010232268/1KD2746924

REAR TAILGATE MECHAISM LOCK <i>Demd</i>	1	263.00	✓ 263.00
REAR TAILGATE MECHANISM LOCK COVER <i>culd</i>	1	98.90	✓ 98.90
REAR TAILGATE OUTER GARNISH <i>culd</i>	1	190.55	✓ 190.55
REAR TAILGATE WEATHER STRIP <i>ut</i>	1	387.60	✓ 387.60
REAR TAILGATE WINDSCREEN SEAL <i>new</i>	1	100.00	60 100.00
REAR TAILLAMP LOWER GARNISH SIDE RETAINER L/R <i>new</i>	2	53.00	x 106.00
Subtotal before discount			7,336.55
Percentage discount 25%			1,834.14
Sub-total 1			5,502.41
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
REAR BUMPER REVERSE SENSOR <i>Demd</i>	1	250.00	200 250.00
REAR END PANEL INNER TOP MOULDING CLIPS - SET <i>new</i>	1	30.00	10 30.00
REAR END PANEL SEALANT <i>new</i>	1	100.00	60 100.00
REAR NUMBER PLATE <i>new</i>	1	25.00	+ 25.00
REAR NUMBER PLATE HOLDER <i>new</i>	1	50.00	+ 50.00
REAR TAILGATE '1250KG' STICKER <i>me</i>	1	50.00	30 50.00
REAR TAILGATE '70KM' STICKER <i>me</i>	1	25.00	15 25.00
REAR TAILGATE WINDSCREEN GLASS SEALANT <i>new</i>	1	80.00	60 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MAHA BODHI SCHOOL BUS SERVICE
 BLK 63 CHAI CHEE ROAD #11-808
 SINGAPORE 460063

Contact : 96625022

TAX INVOICE

Repair Code : CLM17332
 Date in : 11/08/2022
 Vehicle Num. : CB8448T
 Model : TOYOTA HIACE 3.0 DX DIESEL TURBO AT 2WD
 Chassis/Eng# : KDH2010232268/1KD2746924

REAR TAILLAMP CLIPS L/R - SET <i>ms</i>	<i>AIS</i>	2	30.00	<i>10</i> 60.00
Subtotal before discount				720.00
Percentage discount 0%				0.00
Sub-total 2				720.00
Parts-total				6,222.41

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.				<i>60.00</i>
To remove, reinstall tailgate windscreen				<i>120</i> 150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)				<i>60</i> 100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.				<i>800</i> 1,000.00
To remove and reinstall exhaust pipe.			<i>1960</i>	<i>100.00</i>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.				<i>800</i> 1,300.00
To apply anti-rust chemical on repaired and replaced panel.				<i>60</i> 80.00
To remove, reinstall tailgate mechanism and check for function				<i>60</i> 80.00
Labour Total				2,870.00
Parts & Labour Total				9,092.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

page 3

Adrian Lij
N/S 22/08/22
Total: 6476.56 06 Days
N/S 5.1k

*** This is a computer-generated document which requires no signature.***