


VEHICLE DETAIL

Vehicle No	XD 5972 G	SCDF Ref. No.	ACC-IND-22-04
		Adar Form No.	4442

REPAIR DESCRIPTIONS

- 1) Remove & replace dented winch housing chequered sticker(pic 1)
- 2) Remove & wash winch housing sticker adhesive residues (1)
- 3) Panel beat dented winch housing & RH door (pic 1-2)
- 4) Putty & respray RH winch housing & RH door
- 5) Remove & replace damaged front RH corner bumper (pic 3)
- 6) Remove & replace damaged front RH rear view mirror full assy & blind spot mirror (pic 4)
- 7) Remove & replace damaged RH mudguard (pic 5)
- 8) Remove & replace RH boarding step (pic 6)
- 9) Remove & replace RH head lamp (pic 7)
- 10) Remove & replace RH signal lamp (pic 7)

PHOTOS OF DAMAGED PARTS





(pic 7)



XD 5972 G

