

SCOPE OF WORK

- 1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

VEHICLE TYPE	PL	REGISTRATION NO	XD 5972 G	REPAIR TYPE	ACCIDENT
MAKE/MODEL	SCANIA P280	UNIT	STN 22	CONTRACTOR	INDECO

S/N	ITEM DESCRIPTION	PARTS					LABOUR		
		PARTS QTY	PARTS COST PER UNIT (\$)	MARK UP RATE	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	MAN-HOUR RATE (\$)	MAN-HOUR QTY	TOTAL MAN-HOUR COST (\$)
	SCOPE OF REPAIRS								
A	Labour								
1	Remove & replace winch cover chequered sticker							3	
2	Remove & wash winch cover chequered sticker adhesive residues							1	
3	Panel beat damaged winch housing							3	
4	Putty & spray paint winch housing							3	
5	Panel beat dented RH door							2	
6	Putty & respray RH door							3	
7	Remove & replace front RH corner bumper							2	
8	Remove & replace front RH rear view mirror including wiring							2	
9	Remove & replace front RH mudguard							1	
10	Remove & replace front RH boarding step							0.5	
10	Remove & replace front RH head lamp							0.5	
11	Remove & replace front RH signal lamp							0.5	
							SUB TOTAL	21.5	
B	Materials								