



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No.				
			0				
			Document Date				
			23/08/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	ZVW40R	AWXEBW Q4	25/10/2021	SNC4786H	0	17030	66TP/SNC4786H/180822

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EUX0J067858	2ZR2M83903	60	Wang Kang Rong Dion	17/08/2022 10.30	22/08/2022 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TO VEH:GBK1293H ACC DATE:15/08/2022 TP INS: NO OF REPAIR DAYS:4 DATE-IN:17/08/2022 DATE SURVEY:19/08/22 BY:taufikh AUTHORISED ON:19/08/22 -TP/DS CLAIM	*			50.00
2	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.	*			122.40
3	B	BP-LAB2 TO REPLACE/REPAIR FRONT LH ACCIDENT DAMAGE PARTS.STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	*			720.00
4	B	BP-RES2 TO SPRAY PAINT ON FRONT LH SIDE ACCIDENT AFFECTED AREAS.	BP08			1380.00
5	1	U52113-47020 EXTENSION, FR	1.00	36.90		36.90
6	2	U52119-47969 COVER, FR BUMPER	1.00	602.60		602.60
7	3	U75374-47062 EMBLEM, SIDE PANEL	1.00	59.20		59.20

For & on behalf of		Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd				2,971.10
		Please acknowledge receipt of vehicle	Parts 698.70	GST 7.00% 207.98
			Labour 2,272.40	Less 0.00
			Sublet 0.00	
			Lubrication/Fluid 0.00	
			Others 0.00	Amount Due 3,179.08

Customer Copy