

Taufik

CS/CT/22007901/Tgys

[illegible]

Veh No: SMW6795A Yr Regn: 2020 Nov. u

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Audi Q3 C.C 1395.

Colour 50422 A/C: Insured / Std / Ni / NA

Sp. Reading *Green* T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: W144 2727 54M/006450

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

N/S	O/S

Tyre Size: F: 225/60R17
R: 7-1

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. (mm L/Bal. 6 mm

D.O.A. D.O.I. 10/8/22

Survey held at Premkhan Beri

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted: Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐: Prelim. Report

□: Final Report

Days Of Repair: .

Resurvey No. of Trip:

Date/Time. File Return to?

2)

Report Formed :

Lump Sum / E.A. / 16

Add Fee: ☐ : Site Insp (\$

□: Interview (\$

□: Tech. Invs (\$	
-------------------	--

Weekend (\$

Survey Fee:

Transportation:

5) $S \div RS, SI$

1) Photos

Others

TOTAL

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0710/2022/EQ
DATE : 17-Aug-22
WIP : 37651

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 17/8/2022.
YOUR INSURED VEH NO : SLJ 8945 B

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Attn: Motor Claims Dept

OWNER'S NAME : MR. TAN YEW TONG
ADDRESS : 54 CHOA CHU KANG NORTH 7
#09-39
SINGAPORE 689529
TELEPHONE : HP +65 91761860
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070168613
VEHICLE NO : **SMW 6795 A**
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 30/11/2020
ENGINE NO : CZD C04528
CHASSIS NO : WAUZZZF34M1006450
MILEAGE : 50,426 KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Aug-22
PLACE OF ACCIDENT : WOODLAND AVE 9 AND WOODLAND WALK JUNCTION

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6795 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	✓
3	TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00	?
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	?
5	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00	photo?
6	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO REPAIR LHS FRONT DOOR, LHS FRONT FENDER TOP SUPPORT AND LHS UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	Q800/day \$ 7,000.00 2800	
SUB-TOTAL LABOUR CHARGES		: \$ 10,960.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 6795 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, LHS FRONT FENDER, LHS FRONT FENDER TOP SUPPORT, LHS UPPER A-PILLAR AND LHS FRONT DOOR.	\$800 \$ 6,000.00	4500
8	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	?
9	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 17,624.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6795 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	3	\$ 1,301.00	fn ✓
2	FRONT BUMPER GRILLE - CENTER	1	\$ 242.00	an ✓
3	FRONT BUMPER LOWER GRILLE COVER PLATE	1	\$ 58.00	?
4	FRONT BUMPER LOWER GRILLE - LH	1	\$ 124.00	mis ✓
5	FRONT BUMPER CLOSING ELEMENT	1	\$ 212.00	?
6	FRONT BUMPER SPOILER	1	\$ 426.00	fn ✓
7	FRONT BUMPER BRACKET	1	\$ 24.00	?
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 171.00	mis ✓
9	RADIATOR GRILLE	1	\$ 1,594.00	an ✓
10	RADIATOR STRIKER PLATE	1	\$ 271.00	ant ✓
11	FRONT S-LINE EMBLEM	1	\$ 47.00	X
12	FRONT "360" CAMERA COVER CAP	1	\$ 46.00	mis ✓
13	FRONT "360" CAMERA	1	\$ 1,264.00	?
14	FRONT BUMPER FOAM FILLER PIECE	1	\$ 114.00	car ✓
15	FRONT BUMPER CARRIER	1	\$ 974.00	pt ✓
16	FRONT BUMPER GUIDE SECTION - LH	1	\$ 43.00	dis ✓
17	FRONT BUMPER TOP COVER	1	\$ 137.00	ant ✓
18	CAUTION SIGN STICKER	1	\$ 16.00	ne ✓
19	AIR CONDITIONER STICKER	1	\$ 9.00	an ✓
20	HORN SIGNAL HIGH TONE - LH	1	\$ 154.00	ana ✓
SUB TOTAL SPARE PARTS		:	\$ 7,227.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6795 A

DAMAGED PARTS & PRICES				
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET - LH	1	\$ 25.00	bt ✓
22	FRONT PARKING AID SENSOR	1	\$ 797.00	dis ✓
23	FRONT PARKING AID SEAL RING	4	\$ 10.00	new ✓
24	FRONT BUMPER WIRING SET	1	\$ 750.00	in ✓
25	FRONT FENDER - LH	1	\$ 1,445.00	bt ✓
26	FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00	?
27	FRONT FENDER BRACE - LH	1	\$ 98.00	bt ✓
28	FRONT FENDER BRACKET - LH	1	\$ 39.00	?
29	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 37.00	?
30	FRONT FENDER INSULATION - LH	1	\$ 48.00	?
31	FRONT WHEEL HOUSING LINER - LH	1	\$ 260.00	in ✓
32	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 105.00	new ✓
33	FRONT FENDER COVER - LH	1	\$ 18.00	?
34	BONNET	1	\$ 3,695.00	bt ✓
35	BONNET HINGE - LH / RH	2	\$ 162.00	?
36	BONNET ATTACHMENT PARTS	1	\$ 309.00	?
37	BONNET IMPACT PROTECTION - CENTER	1	\$ 31.00	cut ✓
38	BONNET STRIKER - LH	1	\$ 123.00	?
39	FRONT FENDER COVER - LH	1	\$ 46.00	?
40	FRONT PLENUM CHAMBER COVER	1	\$ 144.00	X
SUB TOTAL SPARE PARTS		:	\$ 8,208.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6795 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	BOWDEN CABLE - CENTER	1	\$	64.00	?
42	BOWDEN CABLE COVER	1	\$	11.00	?
43	BONNET LATCH ASSEMBLY	1	\$	228.00	X
44	BONNET RELEASE ELEMENT	1	\$	65.00	?
45	BONNET RELEASE LEVER	1	\$	16.00	?
46	BONNET LOCK CABLE - RH	1	\$	82.00	?
47	BONNET ACTUATING LEVER - RH	1	\$	48.00	?
48	BONNET GAS FILLED STRUT	1	\$	110.00	K
49	BONNET SOUND ABSORBER	1	\$	244.00	X
50	HEADLIGHT MOUNTING - LH / RH	2	\$	264.00	RH X LH ok
51	HEADLIGHT - LH	1	\$	5,952.00	ok
52	HEADLIGHT POWER MODULE - LH	1	\$	850.00	?
53	HEADLIGHT HEAT SINK - LH	1	\$	870.00	?
54	HEADLIGHT HOSE - LH	1	\$	28.00	?
55	HEADLIGHT COMPENSATING PIECE	1	\$	45.00	?
56	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$	462.00	RH X LH dis
57	LIFT CYLINDER HOSE	1	\$	92.00	?
58	LIFT CYLINDER WASH WATER RESEVOIR	1	\$	240.00	dis
59	LIFT CYLINDER CORRUGATED PIPE	1	\$	27.00	?
60	FRONT WHEEL COVER - LH / RH	2	\$	566.00	mis
SUB TOTAL SPARE PARTS		:	\$	10,264.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6795 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	LOCK CARRIER - photo.	1	\$ 1,412.00	dis ✓
62	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 9.00	ok ✓
63	A/C CONDENSER	1	\$ 605.00	?
64	ADDITIONAL RADIATOR	1	\$ 984.00	?
65	RADIATOR RUBBER BUSH	1	\$ 1,093.00	?
66	RUBBER BUSH - UPPER	2	\$ 90.00	?
67	RUBBER BUSH - LOWER	2	\$ 22.00	?
68	RADIATOR AIR GUIDE - LH	1	\$ 43.00	?
69	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 96.00	?
70	RADIATOR COOLANT	6	\$ 297.00	?
71	RADIATOR INTAKE AIR DUCT COVER	1	\$ 30.00	X
72	AIR INTAKE LOWER BRACKET	1	\$ 59.00	X
73	AIR INTAKE INNER BRACKET	1	\$ 21.00	X
74	AIR INTAKE WATER DRAINAGE	1	\$ 23.00	X
75	AIR INTAKE HOSE	1	\$ 36.00	X
76	E BOX - LH	1	\$ 395.00	?
77	FRONT WINDOW SLOT SEAL - LH	1	\$ 251.00	ok X
78	FRONT WINDOW TRIM STRIP - LH	1	\$ 287.00	ok ✓
79	FRONT DOOR COVER - LH	1	\$ 283.00	ok ✓
80	FRONT WINDOW GUIDE - LH	1	\$ 481.00	ok ✓
SUB TOTAL SPARE PARTS		:	\$ 6,517.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 6795 A

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	FRONT NO PLATE	S/N	\$ 60.00	by
82	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 32,776.00	
TOTAL LABOUR CHARGES		:	\$ 17,624.00	
GRAND TOTAL		:	\$ 50,400.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Taufik 99495743/62563561
WP 18/8/12 @ 420pm
Money before paint
Taufik @ LKK auto. car
of days

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT