



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SINGAPORE CIVIL DEFENCE FORCE (MHA05)			Ref:	CS/SCD22007907/Rqy3e2
91 UBI AVE 4 SINGAPORE 408827			Date:	28/09/2022
ATTN: JAMIN TAN			Code:	SCD
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		YN 4655P
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From JAMIN TAN		Assign Date		17/08/2022
2. Vehicle Particulars & Condition				
Make & Model ISUZU		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No. JAANPR85HE7100181		Colour		WHITE
Odometer -		Steering		IN ORDER
Brakes IN ORDER		Modification		NIL
General FAIR				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	7.00-15 LT	SUPER	7 mm
	L/H Front Tyre	7.00-15 LT	SUPER	7 mm
	R/H Rear Tyre	7.00-15 LT (D)	SUPER	7/7 mm
	L/H Rear Tyre	7.00-15 LT (D)	SUPER	7/7 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date		Inspection Date 23/08/2022		
Survey held at 1 Gali Batu Cl, Singapore 728635				
Repairer -				
5a. Remarks				

Registration No. YN 4655P

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
B	MATERIALS					
1	Front Side Corner Panel RH/LH		Cracked			
2	Head lamp RH/LH		Cracked			
3	Signal lamp RH/LH		Cracked			
4	Door Signal Lamp RH		Not Necessary			
5	Front Bumper		Cut			
6	Front Panel		Bent			
7	Front Grille		Cracked			
8	Emblem "ISUZU"		Necessary			
9	RH Mirror Arm Assy		Bent			
10	Blind Spot Mirror		Not Necessary			
11	Front Number Plate		Bent			
12	Front Panel Sticker		Necessary			
A	LABOUR DESCRIPTION					
1	Replace dislodged R/H& L/H corner panel					2
2	Remove & replace shattered R/H & L/H head lamps & signal lamps					4
3	Replace damage front panel cowl cover, radiator grille, cowl top panel, number plate and apply stickers					8
4	Replace damage front bumper & bumper supports					4
5	Replace damage LH blind spot mirror glass					0
6	Remove & replace damage RH mirror arm assy					0.5
7	Re-wiring for head lamps & signal lamps					2

8	Replace front panel sticker and emblem					3
9	Remove & replace number plate					0.5
10	Putty & spray paint front panels					6
COSTING		TOTAL PARTS COST				
		TOTAL MAN-HOUR				30

Registration No. YN 4655P

Vehicle Inspected By



MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor



ADRIAN LING WAI PING
*B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YN 4655P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

