

CVR Accident Photos


VEHICLE DETAIL

Vehicle No	YN 4655 P	Date Of accident	ACC-SMRT-22-02
		Adar Form No.	2160

REPAIR DESCRIPTIONS

1. Replace damage RH / LH corner panels (pic 1-4)
2. Remove & replace shattered RH / LH head lamps (pic 5-6)
3. Remove & replace shattered RH / LH signal lamps (pic 5-6)
4. Remove & replace dented front panel (pic 7-8)
5. Replace front panel sticker & emblem (pic 7-8)
6. Remove & replace radiator grill (pic 8)
7. Remove & replace front dented bumper (pic 9)
8. Remove & replace front dented number plate (pic 9)
9. Remove & replace RH door signal lamp (pic 10)
10. Remove & replace RH mirror arm assy (pic 11)
11. Replace missing blind spot mirror (pic 12)
12. Putty & spray paint front bumper & panel (pic 1-10)

PHOTOS OF DAMAGED PARTS



CVR Accident Photos

