



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207158

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 21/11/2022
Reference CC6/CTI22007909/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SML 7907X
Insured Veh. PD 7700G
Claim No. SNM22D205768/C02
Policy No. DMB1SNW00010722202
Accident Date 15/08/2022
Inspection Date 18/08/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22007909/Kpa3q2	
			Date: 21/11/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PD 7700G	Veh. Inspected	SML 7907X	
Policy No.	DMB1SNW00010722202	Coverage (\$)	0.00	
Claim No.	SNM22D205768/C02	Excess (\$)	0.00	
Assign From		Assign Date	18/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ A180 (A)	c.c	1332	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WDD1770842J074743	Colour	METALLIC PEARL WHITE	
Odometer	40192 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	CONTINENTAL	7 mm	
L/H Front Tyre	205/60 R16	CONTINENTAL	7 mm	
R/H Rear Tyre	205/60 R16	CONTINENTAL	7 mm	
L/H Rear Tyre	205/60 R16	CONTINENTAL	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/08/2022	Inspection Date	18/08/2022	
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SML 7907X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	BUCKLED / CRACKED	1,200.00	1,200.00
1	FRONT BUMPER LOGO EMBLEM	NECESSARY	100.00	100.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	800.00	-
1	FRONT BUMPER ABSORBER FOAM	CRACKED	160.00	160.00
1	FRONT HEADLAMP LH	SERVICEABLE	1,560.00	-
1	FRONT HEADLAMP RH	MTG CRACKED	1,560.00	1,560.00
1	FRONT GRILLE OUTER GARNISH	SERVICEABLE	240.00	-
1	FRONT GRILLE CHROME MOULDING RH	SERVICEABLE	90.00	-
1	FRONT BONNET (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT UPPER AIR DUCT	CRACKED	300.00	300.00
	LESS 10% DISCOUNT		-601.00	-332.00
			5,409.00	2,988.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
			50.00	50.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST FRONT ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT AND FRONT BONNET.		600.00	250.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER ,FRONT BONNET & ETC.		600.00	250.00
	TO DAIGNOSIS FAULT CODE & RESET MEMORY.		150.00	80.00
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		120.00	20.00
			1,470.00	600.00
	GRAND TOTAL		6,929.00	3,638.00

Report Ref No. CC6/CTI22007909/Kpa3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,900.00
---	--	--	-----------------

Report Ref No. CC6/CTI22007909/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 7907X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 7907X

RE-INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SML 7907X

RE-INSPECTION

