



ESTABLISHED 1984

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

INCOME INSURANCE LTD

Ref: CS/INC22007910/Kqy3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 18/10/2022

ATTN: CHESTER CHONG

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	PC 3543A	<b>Veh. Inspected</b>	SGQ 3375B
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1184698-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	DIANA TAY	<b>Assign Date</b>	18/08/2022

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	HONDA STREAM (A)	<b>c.c</b>	1799
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2007
<b>Chassis No.</b>	RN61018207	<b>Colour</b>	BLACK
<b>Odometer</b>	503920 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/65 R15	CST	7 mm
<b>L/H Front Tyre</b>	195/65 R15	CST	7 mm
<b>R/H Rear Tyre</b>	195/65 R15	CST	7 mm
<b>L/H Rear Tyre</b>	195/65 R15	CST	7 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

<b>Accident Date</b>	16/08/2022	<b>Inspect Date / Time</b>	23/08/2022 ( 01:40 PM )
<b>Survey held at</b>	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>6 Working Days</b>
--	-----------------------