

# HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit  
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT  
AUTOWORK PTE LTD

DATE : 17.08.2022

Nett: 22k.

TO : **SOMPO** MOTOR CLAIMS DEPTS  
VEHICLE NO : **YJ9433B**  
MODEL : **MIT-CANTER FEB71ER4SDEC**  
DATE OF ACCIDENT : 17.08.2022  
TIME OF ACCIDENT : 11:00HRS

*ledine.*

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR BACK PILLAR <i>Reps</i>	2	\$ 1,652.30	\$ 3,304.60
2	FRONT DOOR INNER TRIM <i>new</i>	2	\$ 876.90	\$ 1,753.80
3	AIR CLEANER DUCT <i>Deformed.</i>	1	\$ 482.90	\$ 482.90
4	AIR RESONATOR BOX <i>new</i>	1	\$ 864.70	\$ 864.70
5	CABIN BACK PANEL <i>Reps</i>	1	\$ 1,860.00	\$ 1,860.00
6	CABIN BACK PANEL GLASS <i>Shattered</i>	1	\$ 650.00	\$ 650.00
7	CABIN BACK PANEL GLASS MOULDING <i>new</i>	1	\$ 239.00	\$ 239.00
8	CABIN LOCK SYSTEM <i>Not nec.</i>	1	\$ 1,693.70	\$ 1,693.70
9	DASHBOARD <i>new</i>	1	\$ 2,484.71	\$ 2,484.71
10	DASHBOARD CENTER LOWER COVER	1	\$ 496.60	\$ 496.60
11	DASHBOARD SIDE LOWER COVER LH <i>new</i>	1	\$ 286.40	\$ 286.40
12	ENGINE MOUNTING (SET) <i>new</i>	1	\$ 867.30	\$ 867.30
13	TRANSMISSION MOUNTING	1	\$ 359.10	\$ 359.10
14	TAIL LAMP <i>Cracked</i>	2	\$ 360.00	\$ 720.00

143190  
144892

TOTAL PRICE \$ 16,062.81  
LESS 25% \$ 4,015.70  
SUB TOTAL PRICE \$ 12,047.11

## CLAIM DETAILS: SPECIAL NETT

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Dented.</i>	1	\$ 50.00	\$ 50.00
2	REAR REINFORCEMENT <i>Distorted.</i>	1	\$ 2,800.00	\$ 2,800.00
3	REAR NUMBER PLATE LAMP <i>Cracked.</i>	1	\$ 120.00	\$ 120.00
4	TAILGATE WOODEN <i>Distorted.</i>	1	\$ 2,800.00	\$ 2,800.00

1000.  
1800.

TO : **SOMPO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **YJ9433B**  
 MODEL : **MIT-CANTER FEB71ER4SDEC**  
 DATE OF ACCIDENT : 17.08.2022  
 TIME OF ACCIDENT : 11:00HRS

5	TAILGATE HINGE <i>Best</i>	4	\$ 180.00	\$ 720.00	480.
6	TAILGATE '60KM' STICKER <i>3 new</i>	1	\$ 50.00	\$ 50.00	15
7	TAILGATE '22PAX' STICKER	1	\$ 50.00	\$ 50.00	15.
8	SIDE GATE WOODEN <i>noe new</i>	2	\$ 2,800.00	\$ 5,600.00	+
9	SIDE GATE HINGE <i>noe new</i>	6	\$ 180.00	\$ 1,080.00	+
10	REAR WHEEL MUDGUARD <i>torn.</i>	2	\$ 680.00	\$ 1,360.00	900.
11	REAR STEP BRACKET (WOODEN) <i>cracked.</i>	1	\$ 1,500.00	\$ 1,500.00	380.
12	REAR CARGO BED REAR FRAME <i>Best</i>	1	\$ 3,800.00	\$ 3,800.00	1400
13	REAR CARGO BED (WOODEN) <i>3 pillars cracked</i>	5	\$ 2,200.00	\$ 11,000.00	3600
14	REAR CARGO BED BOTTOM BEAMS (WOODEN) <i>5 pillars cracked</i>	9	\$ 1,500.00	\$ 13,500.00	3500.
15	CARGO BED CHASSIS MEMBER (WOODEN) <i>LH cracked.</i>	2	\$ 6,500.00	\$ 13,000.00	900.
16	CARGO BED FRONT PANEL (WOODEN) <i>noe new</i>	1	\$ 4,800.00	\$ 4,800.00	+
17	CARGO BED U CLIP <i>Best.</i>	6	\$ 250.00	\$ 1,500.00	720.
18	CARGO BED FRONT PANEL RAILING (WOODEN) <i>cracked</i>	1	\$ 3,500.00	\$ 3,500.00	1400
19	CARGO BED FRONT PANEL SIDE SUPPORT BRACKET <i>noe new</i>	2	\$ 180.00	\$ 360.00	+
20	CARGO BED FRONT PANEL TOP BEAM <i>noe new</i>	1	\$ 1,600.00	\$ 1,600.00	+
21	CARGO BED SIDE GATE LOCK (FRONT) <i>noe new</i>	2	\$ 180.00	\$ 360.00	+
22	CARGO BED FLOOP COVER PLATE (ALUMINUM) <i>Best.</i>	1	\$ 4,800.00	\$ 4,800.00	1200.
23	CANOPY <i>noe new</i>	1	\$ 5,500.00	\$ 5,500.00	+
24	CANOPY AWRING (SET) <i>noe new</i>	1	\$ 1,200.00	\$ 1,200.00	+
25	TAIL LAMP BACK SUPPORT BRACKET (SPECIAL TYPE) <i>noe new</i>	2	\$ 180.00	\$ 360.00	+

TOTAL \$ 81,410.00

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, KNOCK, WELD, CUT, ADJUST, STRAIGHTEN, GRAZE, ALIGN	\$ 2,000.00	1400
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 2,000.00	900
3	BULB CHECKING, WIRING	\$ 180.00	30
4	REAR CHASSIS ALIGNMENT	\$ 800	400.

17480

TO : **SOMPO** MOTOR CLAIMS DEPTS  
 VEHICLE NO : **YJ9433B**  
 MODEL : **MIT-CANTER FEB71ER4SDEC**  
 DATE OF ACCIDENT : 17.08.2022  
 TIME OF ACCIDENT : 11:00HRS

5	REMOVE AND REFIX ENGINE MOUNTING AND TRANSMISSION MOUNTING	\$ 650.00	X
6	REMOVE AND REFIX CARGO BED	\$ 2,800.00	600
7	REMOVE AND REFIX CANOPY	\$ 800.00	280

**TOTAL 8,630.00**

3610

TOTAL PARTS COST : \$ 93,457.11  
 TOTAL LABOUR COST : \$ 8,630.00  
 TOTAL REPAIR COST : \$ 102,087.11

5310

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

**PARTS PRICES ARE SUBJECT TO CHANGES.**

YOURS FAITHFULLY,

**IRENE**

SERVICE ADVISOR  
 IRENE  
 HP : 8297 9787

total: 22538.92  
 4/s: 18K

10 Days.

18K

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: