

Tropical Tech Automobile Services

Blk. 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535
 Tel: 6481 7773 / 6481 1403 Fax: 6484 4978
 E-mail: tasc303@singnet.com.sg

M/s :

China Taiping Insurance (Singapore) Pte. Ltd
 3, Anson Road, #16-00,
 Springleaf Tower,
 Singapore 079909

Estimate bill :

TT 25 / 22 / TP / WT

Attn :

Motor Claims Third Party Department
 6222 2366
 6224 7175

Registration No :

SFR788U

Make model :

Toyota Wish

Not Attached
L1 Reg & 3150ph
Penney After Paint
5 days

Mileage :

18 / 08 / 2022

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SNC1261A AND SFR788U ALONG YISHUN AVENUE 1 (CROSS JUNCTION BETWEEN YISHUN AVENUE 1 / LENTUR AVE) ON 17 AUGUST 2021 AT ABOUT 1315HRS.

Ipc	Rear windscreen	\$	1,149.00	X
Ipc	Rear windscreen moulding	\$	207.00	
Ipc	Rear boot	\$	1,348.00	
Ipc	Rear boot license lamp outer chrome moulding	\$	230.00	X
Ipc	Rear LH tail lamp	\$	655.00	
Ipc	Rear end panel	\$	1,034.00	
Ipc	Rear bumper	\$	690.00	
Ipc	Rear bumper reflector (LH)	\$	87.00	X
Ipc	Rear bumper side retainer (LH)	\$	121.00	
	Sub A total :	\$	5,521.00	
	Less 25% discount :	\$	1,380.25	
	A total :	\$	4,140.75	

Special net items :

Ipc Rear license smart plate & casing
 Ipc Rear bumper parking sensor kit
 B total :

\$ 35.00 X
 \$ 250.00 X
 \$ 285.00

Remove and refit rear windscreen.

\$ 250.00 *1200*

Total amount for Page 1 :

\$ 4,675.75

Tropical Tech Automobile Services



(Signature)
 (Authorised Signature)
 William Tan

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before clear-spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tropical Tech Automobile Services

Bik 5030, Ang Mo Kio Avenue 3, #01-201, Industrial Park 2, Singapore 569535
Tel : 6481 7773 / 6481 1403 Fax : 6484 4978
E-mail : tasc303@singnet.com.sg

M / s : **China Taiping Insurance (Singapore) Pte. Ltd** Estimate bill : TT 25 / 22 / TP / WT
3, Anson Road, #16-00, Springleaf Tower, Singapore 079909 Registration No : SFR788U
Attn : Motor Claims Third Party Department Make model : Toyota Wish
Tel : 6222 2366
Fax : 6224 7175

Mileage : Date : 18 / 08 / 2022
TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO : SNC1261A AND SFR788U ALONG YISHUN AVENUE 1 (CROSS JUNCTION BETWEEN YISHUN AVENUE 1 / LENTUR AVE) ON 17 AUGUST 2021 AT ABOUT 1315HRS.

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear boot, rear boot license lamp outer chrome moulding, rear LH tail lamp, rear bumper, rear bumper reflector (LH), rear bumper side retailer (LH).

Heat / weld / cut / renew rear end panel, heat / weld / beating rear LH fender, heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment Jack.

To check & refit rear tail lamp wiring harness.

Under coating on vehicle rear portion.

Putty / primer application, spray painting rear boot, rear LH fender, rear end panel, rear bumper.

Balance amount brought from Page 1 :

Grand final amount :

\$	800.00	<i>boal</i>
\$	60.00	<i>2el</i>
\$	200.00	<i>bol</i>
\$	1,600.00	<i>fool</i>
\$	4,675.75	
\$	7,335.75	

Tropical Tech Automobile Services



(Authorised Signature)
William Tan